

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22002998/RGA3Q2**Date:** 23/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0000396_04

Claimant Vehicle No : SKW9558Y **Insured Vehicle No :** SJV2998Z

Date of Loss: 29/03/2022 Nature of Claim: TP Claim No: MPC2022D0001787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW9558Y**

Make & Model: TOYOTA C-HR HYBRID, 1.8 G 5DR (A) Engine No: 2ZRV421641

Reg. Date: 02/06/2017 (Man. Year: 2016) Chassis No: NMTKZ3BX20R012432

Colour: White Odometer: 62935 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 245/40Z R19

Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm

Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,548.00	1,857.12	4,690.88	71.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,000.00	1,490.00	59.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,038.00	2,857.12	6,180.88	68.39
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	9,038.00	2,300.00	6,738.00	74.55
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,787.45		

INSPECTION

Date of Assignment: 31/03/2022

Date Inspected: 04/04/2022 Inspected At:

Pang Hoon Spray Painting (HQ)
BLK 10 ANG MO KIO AUTOPOINT INDUSTRIAL
PARK 2A #04-03
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 G 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW9558Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,020.30 F	*- FL
2	1		*TAILGATE LOCK CATCH	Not Necessary	61.30 F	*- FL
3	1		*TAILGATE GLASS MOLDING	Not Necessary	230.10 F	*- FL
4	1		*TAILGATE TOYOTA LOGO	Not Necessary	56.00 F	*- FL
5	1		*CH-R EMBLEM	Not Necessary	61.70 F	*- FL
6	1		*HYBRID EMBLEM	Not Necessary	53.10 F	*- FL
7	1		*REAR BUMPER	Deformed	489.10 F	*489.10 FL
8	1		*REAR BUMPER BOTTOM	Deformed	570.10 F	*450.00 FL
9	1		*REAR BUMPER LOWER LID	Deformed	420.30 F	*397.60 FL
10	2		*REAR BUMPER REFLECTOR (LEFT & RIGHT)	Not Necessary	420.20 F	*- FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	461.80 F	*- FL
12	2		*REAR BUMPER SIDE BRACKET	Not Necessary	461.80 F	*- FL
13	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	380.00 FS	*200.00 FS
15	1		*REAR BUMPER TOW COVER	Not Necessary	18.90 F	*- FL
16	1		*REAR END PANEL	Repair	789.10 F	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	254.10 F	*254.10 FL
18	1		*REAR LEFT SIDE FENDER PROTECTOR (NPA)	Not Necessary	0.00 F	*- FL
19	8		*REAR LEFT SIDE FENDER PROTECTOR CLIPS (NPA)	Not Necessary	0.00 F	*- FL
20	1		*REAR BUMPER LOWER LIP UNDER BOARD (LEFT SIDE) (NPA)	Not Necessary	0.00 F	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	570.10 F	*352.70 FL
22	1		*REAR KEYLESS SENSOR	Cracked	180.00 F	*180.00 FN
Sub Total (\$\$)						6,548.00 2,373.50
- List Item Discount on L Items 0.00/25.00% (\$\$)						0.00 498.38
- Nett Item Discount on N Items 0.00/10.00% (\$\$)						0.00 18.00
Total Parts (\$\$)						6,548.00 1,857.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE REAR WINDSCREEN	New	180.00	0.00
2	TO APPLY SILICON ONTO REAR WINDSCREEN	New	90.00	0.00
3	LABOUR FOR JACKING ,KNOCKING VEHICLE REAR PORTION ,REPAIR REAR BUMPER ,DISMANTLE & RELACE THE ABOVE AFFECTED PARTS	New	1,000.00	400.00
4	SPRAY PAINTING FOR ALL ACCIDENT AFFECTED PARTS ,REAR BUMPER ,REAR END PANEL & TAILGATE	New	1,100.00	600.00
5	TO APPLY ANTI RUST ON THE ACCIDENT AFFECTED AREA	New	120.00	0.00
Gross Labour Cost (\$)			2,490.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >