

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22003000/EVY3E2

Date: 07/06/2022

REFERENCE

Insured/Claimant: SWC CONSTRUCTION Policy No: DMCVSNW00154852104

Date of Loss: 28/03/2022

Nature of Claim: OD

Claim No: SNM22D202145/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF1228Z**

Make & Model: TOYOTA DYNA 150, 3.0 D (M)

Reg. Date: 30/06/2016 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$50,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2622204

Chassis No: JTFAT35Y10K206547

Odometer: 166422 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,550.00	2,285.00	265.00	10.39
Miscellaneous Items	225.00	145.00	80.00	35.56
Labour	1,402.80	1,260.00	142.80	10.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,177.80	3,690.00	487.80	11.68
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	3,677.80	3,190.00	487.80	13.26
+ GST 7.00/7.00% (S\$)	257.45	223.30	34.15	13.26
Nett Amount (S\$)	3,935.25	3,413.30	521.95	13.26

INSPECTION

Date of Assignment: 31/03/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 01/04/2022 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)

Estimated Period of Repair: 6.0 days
6 Marsiling Lane
Singapore 739145

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Jun 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF1228Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,240.00 F	*1,975.00 F
Supplementary #1						
2	1		*SIDE GARNISH LH	Broken	55.00 F	*55.00 F
3	1		*SIDE GARNISH RH	Broken	55.00 F	*55.00 F
4	1		*SIDE MIRROR COVER LH	Broken	60.00 F	*60.00 F
5	1		*SIDE MIRROR COVER RH	Broken	60.00 F	*60.00 F
6	1		*VACUUM WARN SWITCH	Broken	80.00 F	*80.00 F

F=Franchise part.

Total Parts (S\$)	2,550.00	2,285.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	225.00	145.00
Sub Total (\$\$)			225.00	145.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	961.80	852.60
2	LABOUR FOR SPRAY PAINTING	New	441.00	407.40
Gross Labour Cost (\$\$)			1,402.80	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >