

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003001/EVCE2

Date: 22/07/2022

REFERENCE

Insured/Claimant:	LIM HUI FANG IRA	Policy No:	1700090242		
Date of Loss:	29/03/2022	Nature of Claim:	OD	Claim No:	6198530603SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY8869H	Engine No:	CHZ575944
Make & Model:	AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A)	Chassis No:	WAUZZZ8V7J1022748
Reg. Date:	16/12/2017 (Man. Year: 2017)	Odometer:	70446 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,580.00	16,146.96	7,433.04	31.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,764.00	17,669.00	7,095.00	28.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,344.00	33,815.96	14,528.04	30.05
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	47,744.00	33,215.96	14,528.04	30.43
+ GST 7.00/7.00% (S\$)	3,342.08	2,325.12	1,016.96	30.43
Nett Amount (S\$)	51,086.08	35,541.08	15,545.00	30.43

INSPECTION

Date of Assignment:	31/03/2022		
Date Inspected:	31/03/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	21.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Broken	1,944.00 FS	*1,555.20 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
3	1	*REAR BUMPER ADAPTER - LH / RH	O/S Missing	84.00 FS	*33.60 FS
4	1	*REAR BUMPER GUIDE SECTION - LH / RH	O/S Missing	36.00 FS	*14.40 FS
5	1	*REAR BUMPER LOCKING MECHANISM	Missing	34.00 FS	*26.48 FS
6	1	*REAR BUMPER SPOILER	Cut	264.00 FS	*210.80 FS
7	1	*REAR LIGHT REFLECTOR - RH	Broken	46.00 FS	*36.48 FS
8	1	*TAIL LIGHT OUTER - RH	Cut	974.00 FS	*778.80 FS
9	1	*TAILLIGHT OUTER TRIM - RH	Not Necessary	34.00 FS	*- FS
10	1	*TAIL LIGHT INNER - RH	Cut	974.00 FS	*778.80 FS
11	1	*TAIL LIGHT INNER TRIM - RH	Not Necessary	34.00 FS	*- FS
12	1	*REAR BUMPER REINFORCEMENT BEAM	Dented	642.00 FS	*513.20 FS
13	1	*REAR BUMPER BRACKET - LH / RH (2PCS)	Broken (1Pc Only)	63.00 FS	*25.60 FS
14	1	*REAR BUMPER GUIDE SECTION UPPER - RH	Missing	74.00 FS	*59.20 FS
15	2	*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	530.00 FS	*- FS
16	4	*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
17	1	*SET REAR BUMPER WIRING	Not Necessary	572.00 FS	*- FS
18	1	*REAR LID	Dented	3,657.00 FS	*2,925.60 FS
19	1	*REAR LID ATTACHMENT PARTS	Not Necessary	308.00 FS	*- FS
20	2	*REAR LID HINGE - LH / RH	Not Necessary	570.00 FS	*- FS
21	1	*REAR LID FLAP GASKET	Not Necessary	229.00 FS	*- FS
22	1	*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
23	1	*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
24	1	*A3 EMBLEM	Necessary	104.00 FS	*82.80 FS
25	1	*TFSI EMBLEM	Necessary	104.00 FS	*82.80 FS
26	1	*REAR FENDER - RH	Dented	4,445.00 FS	*3,556.00 FS
27	2	*RIVETTED CAP NUT	Not Necessary	7.00 FS	*- FS
28	1	*REAR WINDSCREEN	Necessary	905.00 FS	*724.00 FS
29	1	*QUARTER WINDOW - RH	Necessary	635.00 FS	*508.00 FS
30	2	*PRIMER	Necessary	44.00 FS	*34.72 FS
31	2	*GROMMET	Not Necessary	4.00 FS	*- FS
32	1	*FUEL INSERT	Necessary	100.00 FS	*79.28 FS
33	1	*BOTTOM PLATE - RH	Dented	206.00 FS	*164.40 FS
34	1	*REAR WHEEL HOUSING LINER PART - RH REAR	Not Necessary	673.00 FS	*- FS
35	1	*REAR WHEEL HOUSING LINER CONNECTING PLATE - RH	Dented	109.00 FS	*86.80 FS
36	1	*D-PILLAR REINFORCEMENT - RH	Dented	305.00 FS	*243.60 FS
37	1	*REAR END PANEL	Dented	379.00 FS	*303.20 FS
38	1	*REAR END PANEL REINFORCEMENT	Dented	773.00 FS	*618.00 FS
39	2	*REAR END PANEL CONNECTING PLATE - LH / RH	Necessary	322.00 FS	*256.80 FS
40	1	*REAR VENT TRIM	Broken	75.00 FS	*59.36 FS
41	1	*AERIAL FOR KESSY	Not Necessary	79.00 FS	*- FS
42	1	*REAR WHEEL HOUSING LINER	Missing	260.00 FS	*208.00 FS
43	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
44	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
45	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
46	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
47	1	*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
48	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
49	1	*SUNDRIES	Necessary	400.00 FS	*69.36 FS
50	1	*LASHING EYE (SUPPLEMENTARY)	Broken	26.00 FS	*20.16 FS
51	1	*LUGGAGE COMPARTMENT TRIM - RH (SUPPLEMENTARY)	Crushed	841.00 FS	*672.80 FS
52	2	*REAR FENDER SOUND ABSORBER (SUPPLEMENTARY)	Necessary	259.00 FS	*207.20 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER	New	600.00	600.00
4	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES	New	400.00	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND LHS 1/4 GLASS	New	200.00	150.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS REAR FENDER, RHS BOTTOM PLATE, RHS D-PILLAR REINFORCEMENT AND RHS WHEEL HOUSING OUTER. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,100.00	6,000.00
9	TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, FUEL CAP, RHS D-PILLAR REINFORCEMENT, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE PANEL SPARE WHEEL HOUSING AND REAR END PANELLING	New	7,000.00	3,575.00
10	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	800.00
11	TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
12	TO TOW BACK THE VCHIEL FROM ACCIDENT SCENE	New	280.00	0.00
13	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			24,764.00	17,669.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >