



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1024A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WING MIRROR ASSY LH W/O GLASS	TO REPAIR SEE LABOUR	620.00	-
1	GLASS LH, WING MIRROR	SERVICEABLE	320.00	-
1	W/MIRROR BOTTOM LAMP LH - M08	SERVICEABLE	60.00	-
1	LAMP LH, WING MIRROR	SERVICEABLE	138.00	-
1	DOOR ASSY - LHR	TO REPAIR SEE LABOUR	1,612.00	-
1	WEATHERSTRIP - BODY RH/LH REAR DOOR	NECESSARY	226.00	226.00
1	PANEL - LH FRT SIDE BODY	DENTED	2,900.00	2,900.00
1	WEATHERSTRIP - RH/LH FRT/RR DOOR	SERVICEABLE	220.00	-
			6,096.00	3,126.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIX DOOR LH.		150.00	150.00
	TO SPRAY PAINT DORR, ROOF TOP SIDE PANEL AND WING MIRROR.		525.00	525.00
	TO SUPPLY SEALANT.		60.00	60.00
	TO CUT AND REPLACE LEFT SIDE FRONT BODY PANEL, INCLUSIVE OF THE REPAIR OF WING MIRROR ASSY LH W/O GLASS, DOOR ASSY - LHR.		2,400.00	1,800.00
			3,135.00	2,535.00
	GRAND TOTAL		9,231.00	5,661.00
	RECOMMENDED COST OF REPAIRS			5,661.00

Report Ref No. CC2/MIDA22003009/Tp

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.