

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003011/AVY3E2**Date:** 19/06/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00111462109
Claimant Vehicle No :	JPX5898	Insured Vehicle No :	SKF6194Y
Date of Loss:	06/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201615/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPX5898	Engine No:	ZR800AEA12702
Make & Model:	KAWASAKI ZR800B, 806cc	Chassis No:	JKBZR800AADA08438
Reg. Date:	11/02/2014 (Man. Year: 2013)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	806 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	180/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,479.00	7,272.90	2,206.10	23.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	740.00	570.00	43.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,789.00	8,012.90	2,776.10	25.73
Approved Total (Overridden) (S\$)		6,400.00		
Nett Amount (S\$)	10,789.00	6,400.00	4,389.00	40.68

INSPECTION

Date of Assignment:	01/04/2022	
Date Inspected:	31/03/2022	Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	KAWASAKI ZR800B 806cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPX5898)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIM	Bent	880.00 F	*880.00 FL
2	1		*FRONT WHEEL SHAFT	Bent	48.00 F	*48.00 FL
3	2		*FRONT BRAKE DISC L&R (BRAKING DISC)	Not Necessary	720.00 F	*- FL
4	1		*FRONT AXLE SLIDER R&G	Cut	120.00 F	*120.00 FL
5	1		*FRONT MUDGUARD	Cracked	220.00 F	*220.00 FL
6	1		*SET FRONT FORK COMPLETE L&R	Bent	2,800.00 F	*2,800.00 FL
7	1		*STEERING STREM	Necessary	480.00 F	*480.00 FL
8	1		*STEERING CONE BEARING	Necessary	220.00 F	*220.00 FL
9	1		*STEERING TOP TAPE	Damaged	300.00 F	*300.00 FL
10	1		*HEADLAMP	Cracked	495.00 F	*495.00 FL
11	1		*HEAD FAIRING	Cracked	210.00 F	*210.00 FL
12	1		*WINDSCREEN (PLUG)	Cracked	210.00 F	*210.00 FL
13	2		*FRONT SIGNAL L&R	Not Necessary	98.00 F	*- FL
14	1		*HEAD COWLING CARBON COVER L&R	Cut	260.00 F	*260.00 FL
15	1		*HANDLE BAR	Bent	175.00 F	*175.00 FL
16	1		*HANDGUARD LEVER L&R	Cut	98.00 F	*98.00 FL
17	1		*BREMBO RCS CLUTCH MOUNT BRACKET	Cracked	28.00 F	*28.00 FL
18	2		*MIRROR L&R	Damaged	140.00 F	*140.00 FL
19	1		*FRAME SLIDERS R&G	Cut	195.00 F	*195.00 FL
20	1		*REAR FAIRING WHOLE PCS	Cracked	395.00 F	*395.00 FL
21	1		*REAR NUMBER PLATE	Not Necessary	40.00 F	*- FL
22	1		*REAR NUMBER TAIL TIDY BRACKET	Not Necessary	120.00 F	*- FL
23	1		*MAGNETO COVER R&G	Not Necessary	160.00 F	*- FL
24	1		*BREMBO RCS16 CLUTCH	Damaged	495.00 F	*495.00 FL
25	1		*FUEL TANK LOWER RIGHT FAIRING BLACK	Damaged	240.00 F	*240.00 FL
26	2		*FUEL TANK COVER L&R MATT BLACK	Not Necessary	260.00 F	*- FL
27	1		*FUEL TANK (KAWASAKI EMBLEM L&R)	Necessary	72.00 F	*72.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	9,479.00	8,081.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	808.10
Total Parts (\$)	9,479.00	7,272.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOW	New	60.00	40.00
2	LABOUR	New	550.00	400.00
3	SPRAY PAINTING	New	400.00	200.00
4	TO STRAIGHTEN BODY CHASSIS	New	300.00	100.00
Gross Labour Cost (\$\$)			1,310.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >