

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO22003015/Kvy3e2 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 13/04/2022 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SMC 5056L PC 9599A Veh. Inspected Policy No. S21MTPV01008120 Coverage (\$) 0.00 Claim No. CMTD2201075/THE Excess (\$) 0.00 **GRACE TEO Assign Date** 31/03/2022 Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI ROSA (A) Make & Model 2998 C.C 2015 HIDDEN Engine No. Year of Reg. BE641JK30014 WHITE Chassis No. Colour 412165 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/75 R17.5 LING LONG 10 mm 215/75 R17.5 LING LONG L/H Front Tyre 10 mm 215/75 R17.5 (D) BRIDGESTONE R/H Rear Tyre 3/3 mm 215/75 R17.5 (D) BRIDGESTONE L/H Rear Tyre 3/3 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. 5. **General Information** 29/03/2022 07/04/2022 (11:16 AM) Inspect Date / Time Accident Date CROWN ASIA BUS BUILDER PTE LTD Survey held at NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 4 Working Days

Report Ref No. CS3/SMO22003015/Kvy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

DECD Ante Consultant CAE Lineared American

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE