



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 361B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR MUDGUARD,RH @\$595.50 (CONSISTENT)	TO REPAIR SEE LABOUR	591.00	-
	LESS 25% DISCOUNT		-147.75	-
			443.25	-
1	RUBBER STOPPER (SN)(CONSISTENT)	MISSING	145.50	50.00
	LESS 25% DISCOUNT		-36.38	-
			109.12	50.00
	<u>LABOUR</u>			
	TO PANEL BEAT RHS BODY.TO DISMANTLE/REPLACE ABOVE-MENTIONED PARTS.TO DISMANTLE/REFIX DIESEL TANK.INCLUSIVE OF THE REPAIR REAR MUDGUARD,RH.		500.00	350.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		450.00	400.00
	TO REDO ADVERTISING LOGO.		180.00	180.00
			1,130.00	930.00
GRAND TOTAL			1,682.37	980.00
RECOMMENDED COST OF REPAIRS				980.00

Report Ref No. CC4/ASM22003016/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.