

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22003021/KQY3E2

Date: 23/05/2022

REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD
Date of Loss: 27/03/2022

Policy No: 102726
Nature of Claim: OD Claim No: MFL2022D0001763

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR3647R**
Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G19800
Reg. Date: 31/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU903090536
Colour: Metallic Silver Odometer: 185796 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$112,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Davanti 9 mm Rear Left Side: Davanti 9 mm
Front Right Side: Davanti 9 mm Rear Right Side: Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,880.61	10,649.79	7,230.82	40.44
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,900.00	1,820.00	1,080.00	37.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,791.61	12,480.79	8,310.82	39.97
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	20,791.61	10,980.79	9,810.82	47.19
+ GST 7.00/7.00% (S\$)	1,455.41	768.66	686.75	47.19
Nett Amount (S\$)	22,247.02	11,749.45	10,497.57	47.19

INSPECTION

Date of Assignment: 01/04/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected: 01/04/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR3647R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	993.70 FL	*993.70 FL
2	1		*BONNET LOCK	Bent	145.90 FL	*145.90 FL
3	1		*BONNET HINGE LH	Distorted	65.20 FL	*65.20 FL
4	1		*BONNET HINGE RH	Distorted	65.20 FL	*65.20 FL
5	10		*BONNET INSULATOR	Serviceable	1,456.00 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Necessary	7.20 FL	*7.20 FL
7	1		*HEADLAMP LH	Cracked	2,661.70 FL	*2,661.70 FL
8	1		*HEADLAMP LOWER BRACKET LH	Serviceable	79.00 FL	*- FL
9	1		*HEADLAMP RH	Cracked	2,661.70 FL	*2,661.70 FL
10	1		*HEADLAMP LOWER BRACKET RH	Serviceable	79.00 FL	*- FL
11	1		*FRT GRILLE	Cracked	349.50 FL	*349.50 FL
12	1		*FRT GRILLE LOGO	Necessary	125.60 FL	*125.60 FL
13	1		*FRT GRILLE LOGO LOWER GARNISH	Distorted	96.00 FL	*96.00 FL
14	1		*FRT BUMPER	Buckled	556.20 FL	*556.20 FL
15	1		*FRT BUMPER SIDE RETAINER LH	Distorted	85.20 FL	*85.20 FL
16	1		*FRT BUMPER SIDE RETAINER RH	Distorted	85.20 FL	*85.20 FL
17	1		*FRT BUMPER SPONGE	Cracked	88.20 FL	*88.20 FL
18	1		*FRT BUMPER UPPER REINFORCEMENT	Repair	716.60 FL	*- FL
19	1		*FRT BUMPER LOWER REINFORCEMENT	Repair	240.10 FL	*- FL
20	1		*FRT BUMPER TOW COVER RH	Missing	32.60 FL	*32.60 FL
21	1		*FRT BUMPER TOW COVER LH	Serviceable	32.60 FL	*- FL
22	1		*FRT BUMPER LOWER GRILLE	Serviceable	187.20 FL	*- FL
23	1		*FRT BUMPER TOP RUBBER	Necessary	88.00 FL	*88.00 FL
24	1		*FRT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
25	1		*FRT NUMBER PLATE BASE(LONG)	Cracked	115.60 FL	*115.60 FL
26	1		*FRT SUPPORT TOP PANEL CENTER	Buckled	379.60 FL	*379.60 FL
27	1		*FRT SUPPORT TOP PANEL RH	Buckled	80.00 FL	*80.00 FL
28	1		*FRT SUPPORT TOP PANEL LH	Buckled	80.00 FL	*80.00 FL
29	1		*FRT SUPPORT SIDE PANEL RH	Bent	255.00 FL	*255.00 FL
30	1		*FRT SUPPORT SIDE PANEL LH	Repair	255.00 FL	*- FL
31	1		*FRT SUPPORT LOWER PANEL	Repair	435.00 FL	*- FL
32	1		*FRT BRACE PANEL	Repair	85.90 FL	*- FL
33	1		*FRT SUPPORT TOP GARNISH	Serviceable	283.90 FL	*- FL
34	1		*AIRCON CONDENSOR	Serviceable	1,789.30 FL	*- FL
35	1		*RADIATOR	Serviceable	2,218.90 FL	*- FL
36	1		*RADIATOR FAN COWLING	Serviceable	264.80 FL	*- FL
37	1		*RADIATOR FAN MOTOR	Serviceable	702.80 FL	*- FL
38	1		*RADIATOR FAN BLADE	Serviceable	219.00 FL	*- FL
39	1		*FRT RH LOWER SIDE AIR GUIDE	Cracked	76.00 FL	*76.00 FL
40	1		*FRT LH LOWER SIDE AIR GUIDE	Distorted	76.00 FL	*76.00 FL
41	1		*LH TOP SIDE AIR GUIDE	Serviceable	84.00 FL	*- FL
42	1		*RH TOP SIDE AIR GUIDE	Serviceable	84.00 FL	*- FL
43	1		*RH HORN	Serviceable	146.00 FL	*- FL
44	1		*LH HORN	Serviceable	146.00 FL	*- FL
45	1		*COOLANT	Necessary	58.00 FL	*58.00 FL
46	1		*AIR DUCT	Cracked	156.00 FL	*156.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*AIR INTAKE DUCT	Serviceable	136.00 FL	*- FL
48	1		*LH FRT FENDER	Buckled	1,037.80 FL	*1,037.80 FL
49	1		*LH FRT FENDER EMBLEM HYBRID	Necessary	68.00 FL	*68.00 FL
50	1		*RH FRT FENDER	Buckled	1,037.80 FL	*1,037.80 FL
51	1		*RH FRT FENDER EMBLEM HYBRID	Necessary	68.00 FL	*68.00 FL
Supplementary #2						
52	1		*HEADLAMP CONTROL UNIT (HID) LH	Dented	2,544.82 FL	*2,544.82 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,825.82	14,184.72
- List Item Discount on L Items 25.00/25.00% (\$)	5,945.21	3,534.93
Total Parts (\$)	17,880.61	10,649.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL, RH FRT FENDER, LH FRT FENDER, BOTH HEADLAMPS AND ETC	New	1,200.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS BONNET, FRT BUMPER, FRT SUPPORT PANEL, RH FRT FENDER, LH FRT FENDER AND ETC	New	1,300.00	1,000.00
3	TO DISCHARGE AND CHARGE AIRCON GAS	New	100.00	100.00
4	TO CHECK WIRING AND LIGHTING	New	50.00	20.00
5	TO PROGRAM AND RESET HEADLAMP SYSTEM	New	250.00	100.00
			Gross Labour Cost (\$\$)	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >