

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003022/AVCE2

Date: 24/08/2022

REFERENCE

Insured/Claimant:	CHEOK SUAT LEE	Policy No:	1800055715-03		
Date of Loss:	25/03/2022	Nature of Claim:	OD	Claim No:	5095685241SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN8881Z		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX033228
Reg. Date:	17/05/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF3J2141016
Colour:	Blue	Odometer:	13027 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,409.00	18,826.48	8,582.52	31.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,252.00	12,587.00	8,665.00	40.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,661.00	31,413.48	17,247.52	35.44
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	46,861.00	29,613.48	17,247.52	36.81
+ GST 7.00/7.00% (S\$)	3,280.27	2,072.94	1,207.33	36.81
Nett Amount (S\$)	50,141.27	31,686.42	18,454.85	36.81

INSPECTION

Date of Assignment:	01/04/2022		
Date Inspected:	31/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,030.00 FS	*1,624.00 FS
2	1		*REAR BUMPER TAIL LIGHT - LH	Not Necessary	779.00 FS	*- FS
3	1		*TAIL LIGHT - LH	Cut	1,859.00 FS	*1,487.20 FS
4	1		*REAR BUMPER GUIDE SECTION - LH	Damaged	95.00 FS	*75.28 FS
5	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,230.00 FS	*984.00 FS
6	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
7	1		*REAR FENDER - LH	Dented	5,267.00 FS	*4,213.60 FS
8	1		*QUARTER WINDOW - LH	Necessary	925.00 FS	*740.00 FS
9	1		*REAR DOOR - LH	Distorted	4,390.00 FS	*3,512.00 FS
10	1		*REAR DOOR SEAL BRACKET	Not Necessary	48.00 FS	*- FS
11	1		*REAR DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
12	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
14	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
15	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
16	1		*GROMMET	Not Necessary	10.00 FS	*- FS
17	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	231.00 FS	*- FS
18	1		*REAR DOOR CATCH - LH	Not Necessary	163.00 FS	*- FS
19	1		*REAR DOOR SEAL OUTER - LH	Not Necessary	247.00 FS	*- FS
20	2		*REAR DOOR HINGE HALF UPPER / LOWER - LH	Not Necessary	106.00 FS	*- FS
21	1		*REAR DOOR SEAL INNER - LH	Not Necessary	229.00 FS	*- FS
22	1		*REAR DOOR HANDLE MOUNTING BAR - LH	Not Necessary	183.00 FS	*- FS
23	1		*REAR DOOR WINDOW REGULATOR - LH	Not Necessary	334.00 FS	*- FS
24	1		*REAR DOOR SILL TRIM STRIP - LH	Necessary	158.00 FS	*126.40 FS
25	1		*REAR DOOR COVER - LH	Necessary	728.00 FS	*582.40 FS
26	1		*FRONT DOOR - LH	Distorted	4,390.00 FS	*3,512.00 FS
27	1		*FRONT DOOR BUNGS - LH	Not Necessary	5.00 FS	*- FS
28	1		*FRONT DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
29	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
30	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
31	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
32	5		*GROMMET	Not Necessary	16.00 FS	*- FS
33	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	276.00 FS	*- FS
34	1		*FRONT DOOR CATCH - LH	Not Necessary	163.00 FS	*- FS
35	1		*FRONT DOOR COVER - LH	Necessary	833.00 FS	*666.40 FS
36	1		*FRONT DOOR HANDLE TRIM PLATE - PASSENGER SIDE	Not Necessary	306.00 FS	*- FS
37	1		*FRONT DOOR HOUSING - PASSENGER SIDE	Not Necessary	20.00 FS	*- FS
38	1		*FRONT DOOR HANDLE COVER - LH	Not Necessary	7.00 FS	*- FS
39	1		*FRONT DOOR HANDLE MOUNTING BAR - PASSENGER SIDE	Not Necessary	183.00 FS	*- FS
40	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
41	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
42	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
43	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
44	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
45	1		*SUNDRIES	Necessary	500.00 FS	*57.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 27,409.00 18,826.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER	New	300.00	300.00
3	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	4,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR HANDLE, LHS REAR DOOR, LHS FRONT DOOR, 2 DOOR COVERS, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE, REAR END PANELLING AND BOTH REAR WHEEL ARCHTRIMS	New	9,000.00	3,825.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			21,252.00	12,587.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >