

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003025/AQCE2**Date:** 04/10/2022**REFERENCE**

| | | | | |
|-------------------|--------------|------------------|------------|------------------------|
| Insured/Claimant: | CHEN JUNMING | Policy No: | 2070177852 | |
| Date of Loss: | 24/03/2022 | Nature of Claim: | OD | Claim No: 4704030103SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SMX616T | | |
| Make & Model: | AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A) | Engine No: | DKJ052759 |
| Reg. Date: | 23/12/2020 (Man. Year: 2020) | Chassis No: | WAUZZZGB9LR044567 |
| Colour: | Red | Odometer: | 23459 km |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | S\$120,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195/55R16 | Rear Tyre Size: | 195/55R16 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 5,514.00 | 0.00 | 5,514.00 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,922.00 | 1,600.00 | 4,322.00 | 72.98 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,436.00 | 1,600.00 | 9,836.00 | 86.01 |
| - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (S\$) | 10,836.00 | 1,000.00 | 9,836.00 | 90.77 |
| + GST 7.00/7.00% (S\$) | 758.52 | 70.00 | 688.52 | 90.77 |
| Nett Amount (S\$) | 11,594.52 | 1,070.00 | 10,524.52 | 90.77 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 01/04/2022 | | |
| Date Inspected: | 31/03/2022 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|---------------------------|---------------|-------------|--------|
| 1 | 1 | | *REAR DOOR-RH | Repair | 3,348.00 FS | *- FS |
| 2 | 1 | | *REAR DOOR CATCH-RH | Not Necessary | 99.00 FS | *- FS |
| 3 | 1 | | *REAR STONE CHIP GUARD-RH | Not Necessary | 493.00 FS | *- FS |
| 4 | 1 | | *REAR WHEEL HOUSING LINER | Not Necessary | 198.00 FS | *- FS |
| 5 | 1 | | *REAR ALUMINIUM RIM | Not Necessary | 1,076.00 FS | *- FS |
| 6 | 1 | | *SUNDRIES | Not Necessary | 300.00 FS | *- FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (S\$) | | | | | 5,514.00 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES | New | 350.00 | 0.00 |
| 2 | TO DISMANTLE AND RENEW RHS REAR DOOR.TO REPAIR RHS REAR FENDER.TO REMOVE AND REINSTALL RHS SILL PANEL TRIM.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 2,100.00 | 500.00 |
| 3 | TO RESPRAY RHS REAR DOOR,RHS REAR FENDER AND RHS SILL PANEL TRIM | New | 3,000.00 | 1,100.00 |
| 4 | TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 0.00 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 5,922.00 | 1,600.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >