

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21011831/GTY3E2-1

Date: 10/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMT1534K **Insured Vehicle No :** SLQ8341G
Date of Loss: 19/11/2021 Nature of Claim: TP Claim No: MFL2021D0005027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT1534K**
Make & Model: MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A) Engine No: 27491030012023
Reg. Date: 01/11/2012 (Man. Year: 2012) Chassis No: WDD2040312A760865
Colour: Silver Odometer: 148283 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,013.98	5,078.99	9,934.99	66.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,840.00	1,870.00	50.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,723.98	6,918.99	11,804.99	63.05
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	18,723.98	5,500.00	13,223.98	70.63
+ GST 7.00/7.00% (S\$)	1,310.68	385.00	925.68	70.63
Nett Amount (S\$)	20,034.66	5,885.00	14,149.66	70.63

INSPECTION

Date of Assignment: 31/03/2022
Date Inspected: 22/11/2021 Inspected At: JP Conceptz Pte Ltd (HQ)
160 Sin Ming Drive #07-07, AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 May 2022)

Parts: 143 MERCEDES-BENZ C180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMT1534K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEADLAMP ASSEMBLY N/S	Base cracked/displaced	2,501.00 F	*1,872.60 FL
2	1	*FRONT BUMPER (Securing hook snapped)	Badly grazed	1,069.52 F	*1,069.52 FL
3	1	*FRONT BUMPER FOG LAMP HOUSING N/S	Serviceable	234.71 F	*- FL
4	1	*FRONT BUMPER CHROME STRIP N/S	Essential	65.75 F	*65.75 FL
5	1	*FRONT BUMPER CORNER BRACKET N/S	Twisted	41.41 F	*41.41 FL
6	1	*FRONT FENDER N/S	Dented / Buckled	722.65 F	*722.65 FL
7	1	*FRONT FENDER INNER SHIELD N/S	Serviceable	127.59 F	*- FL
8	1	*FRONT FENDER CHROME STRIP N/S	Essential	51.11 F	*51.11 FL
9	1	*FRONT ALLOY RIM N/S	Badly scratched	889.60 F	*889.60 FL
10	1	*FRONT SHOCK ABSORBER N/S	Serviceable	571.50 F	*- FL
11	1	*FRONT LOWER ARM N/S	Serviceable	479.10 F	*- FL
12	1	*FRONT KNUCKLE N/S	Serviceable	901.40 F	*- FL
13	1	*FRONT DOOR MIRROR GLASS N/S	Serviceable	190.62 F	*- FL
14	1	*FRONT DOOR MIRROR HOUSING C/W SIGNAL LAMP N/S	Cracked	363.70 F	*363.70 FL
15	1	*FRONT DOOR MIRROR MOTOR ASSEMBLY N/S	Serviceable	272.29 F	*- FL
16	1	*FRONT DOOR N/S	Repair	1,508.80 F	*- FL
17	1	*FRONT DOOR WINDOW GLASS OUTER MOULDING N/S	Serviceable	90.74 F	*- FL
18	1	*FRONT DOOR CHROME STRIP N/S	Essential	124.52 F	*124.52 FL
19	1	*FRONT DOOR DRAUGHT WEATHERSTRIP N/S	Serviceable	213.26 F	*- FL
20	1	*REAR DOOR N/S	Repair	1,534.99 F	*- FL
21	1	*REAR DOOR WINDOW GLASS OUTER MOULDING N/S	Serviceable	104.69 F	*- FL
22	1	*REAR DOOR CHROME STRIP N/S	Essential	114.68 F	*114.68 FL
23	1	*REAR DOOR DRAUGHT WEATHERSTRIP N/S	Serviceable	213.26 F	*- FL
24	1	*REAR FENDER N/S	Repair	1,794.68 F	*- FL
25	1	*REAR WINDSCREEN MOULDING	Serviceable	172.41 F	*- FL
26	1	*FRONT TYRE [DUNLOP: 225/45R17] N/S (30%DEP)	Cut	350.00 FS	*245.00 FS
27	1	*SET FRONT BUMPER CLIP/FASTENER	Essential	50.00 FS	*30.00 FS
28	1	*FRONT FENDER INNER SHIELD CLIP/FASTENER N/S	Essential	40.00 FS	*20.00 FS
29	1	*FRONT DOOR INNER TRIM BOARD CLIP/FASTENER N/S	Serviceable	40.00 FS	*- FS
30	1	*REAR DOOR INNER TRIM BOARD CLIP/FASTENER N/S	Serviceable	40.00 FS	*- FS
31	1	*REAR FENDER INNER TRIM CLIP/FASTENER N/S	Serviceable	40.00 FS	*- FS
32	1	*REAR WINDSCREEN SEALANT/REPAIR KIT	Serviceable	60.00 FS	*- FS
33	1	*REAR WINDSCREEN DAM KIT/INNER SEAL	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,013.98	5,610.54
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	531.55
Total Parts (\$\$)	15,013.98	5,078.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS	New	50.00	30.00
2	TO DISMANTLE / TRANSFER N/S FRONT & REAR DOOR FITTINGS / AUCILLARY ACCESSORIES ETC. TO NEW DOOR UNITS	New	360.00	0.00
3	TO DISMANTLE / INSTALL REAR WINDSCREEN TO FACILITATE REPAIRS INCLUDING TO CONDUCT FOR WATER LEAKAGES ETC	New	150.00	0.00
4	TO DISMANTLE / INSTALL REAR LUGGAGE FITTINGS / ANCILLARY ATTACHMENTS, REAR SPEAKER BOARD, TRIMS, GARNISHES, REAR SEAT, BACK-REST, ROOF-LININGS, ETC. TO FACILITATE REPAIRS	New	180.00	0.00
5	TO DISMANTLE / CHECK / RENEW N/S FRONT SUSPENSION MEMBERS TO FACILITATE REPAIRS	New	350.00	0.00
6	TO CORRECT FRONT WHEEL GEOMETRY INCLUDING TO OSCILLATE / EQUIPOISE N/S FRONT ALLOY RIM / TYRE TO SPECIFICATIONS	New	120.00	60.00
7	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYRETHANE PAINT }	New	1,500.00	1,150.00
8	TO DO RUSTPROOFING AND CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS }	New	0.00	0.00
9	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE, RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DISMENSIONS	New	1,000.00	600.00
Gross Labour Cost (S\$)			3,710.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >