

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003030/RNY3M4**Date:** 05/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00036192200
Claimant Vehicle No :	SMQ5953Z	Insured Vehicle No :	GBH2060Y
Date of Loss:	29/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202189/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5953Z	Engine No:	160831W0972204DTD
Make & Model:	JAGUAR XE 2.0 I4D TSS, 2.0 D (A)	Chassis No:	SAJAB4AN9HCP03110
Reg. Date:	11/01/2017 (Man. Year: 2016)	Odometer:	75752 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,592.50	3,923.46	7,669.04	66.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,121.00	5,721.00	2,400.00	29.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,713.50	9,644.46	10,069.04	51.08
+ GST 7.00/7.00% (S\$)	1,379.95	675.11	704.84	51.08
Nett Amount (S\$)	21,093.45	10,319.57	10,773.88	51.08

INSPECTION

Date of Assignment:	04/04/2022	
Date Inspected:	01/04/2022 Inspected At:	WEARNES AUTOMOTIVE PTE LTD (LENG KEE) 45 LENG KEE ROAD SINGAPORE 159103
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jul 2022)	
Parts:	N/A	JAGUAR XE 2.0 I4D TSS 2.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5953Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LIP XE	Bent	1,696.80 FS	*1,527.12 FS
2	1		*SEAL-TRUNK LID	Not Necessary	250.80 FS	*- FS
3	1		*BOOTH LATCH XE XF	Not Necessary	322.90 FS	*- FS
4	1		*TRUNK LIP BEZEL XE X	Not Necessary	25.20 FS	*- FS
5	1		*ACTUATOR	Not Necessary	173.40 FS	*- FS
6	1		*COVER	Not Necessary	18.90 FS	*- FS
7	1		*BADGE REAR XE	Necessary	125.00 FS	*112.50 FS
8	1		*BADGE	Necessary	228.90 FS	*206.01 FS
9	1		*BADGE	Necessary	120.30 FS	*108.27 FS
10	1		*FOG LAMP REAR LH XE	Not Necessary	398.30 FS	*- FS
11	1		*LAMP-TAIL LH	Not Necessary	553.90 FS	*- FS
12	1		*COVER-BUMPER REAR	Deformed	1,225.00 FS	*1,102.50 FS
13	1		*PANEL-VALANCE REAR	Cracked	563.60 FS	*507.24 FS
14	1		*TOW COVER REAR XE	Not Necessary	34.40 FS	*- FS
15	1		*CAP-END RH	Not Necessary	22.20 FS	*- FS
16	1		*CAP-END LH	Not Necessary	22.20 FS	*- FS
17	15		*BUMPER NUT XF	Necessary	79.50 FS	*71.55 FS
18	1		*MOUNTING BRACKET CEN	Not Necessary	158.50 FS	*- FS
19	1		*MOUNTING-BRACKET LH	Not Necessary	132.90 FS	*- FS
20	1		*BUMPER BEAM REAR XE	Not Necessary	696.50 FS	*- FS
21	1		*ANTENNA	Not Necessary	42.80 FS	*- FS
22	1		*PARKING AID SENSOR R (6PCS)	Not Working (1Piece Only)	1,627.80 FS	*244.17 FS
23	1		*PIPE & SILENCER	Not Necessary	1,742.30 FS	*- FS
24	1		*CLAMP	Not Necessary	92.20 FS	*- FS
25	1		*HEATSHIELD LH	Not Necessary	60.20 FS	*- FS
26	1		*HEATSHIELD LH	Not Necessary	248.10 FS	*- FS
27	1		*UNDERTRAY LH	Not Necessary	442.80 FS	*- FS
28	1		*UNDERTRAY RH	Not Necessary	443.00 FS	*- FS
29	1		*SEAM SEALANT	Necessary	49.00 FL	*49.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,597.40	3,928.36
- List Item Discount on L Items 10.00/10.00% (S\$)	4.90	4.90
Total Parts (S\$)	11,592.50	3,923.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BOOTLID, REAR BUMPER REINFORCEMENT, EMBLEM, BOOTLID LAMP LH, TAIL LAMP LH, ETC	New	3,000.00	2,600.00
2	TO SPRAY BOOTLID, REAR BUMPER, ETC	New	2,500.00	2,000.00
3	TO REMOVE & TRANSFER BOOTLID INTERIOR COMPONENTS	New	500.00	500.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
5	TO REPLACE EXHAUST PIPE, ETC	New	1,500.00	0.00
Gross Labour Cost (\$)			8,121.00	5,721.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >