

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INS	PECTION RE	PORT		
	SOMPO INSURAN	ICE SINGAPORE PL		Ref:	CS3/SMO22003033/Uqy3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND DRE 048623		Date:	28/04/2022	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBB 4932A	Veh. Inspected	ł	SKT 7985B	
	Policy No.	D21MTPCVE001300	Coverage (\$)		0.00	
	Claim No.	CMTD2201084/MYE	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		01/04/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	VOLVO S60 (A)	c.c		1560	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	YV1FS84ABF2365887	Colour		GREY	
	Odometer	77501 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 R16	MICHELIN		7 mm	
	L/H Front Tyre	215/55 R16	MICHELIN		7 mm	
	R/H Rear Tyre	215/55 R16	MICHELIN		7 mm	
	L/H Rear Tyre	215/55 R16	MICHELIN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	30/03/2022	Inspect Date /	Time	01/04/2022 (11:20 AM)	
	Survey held at	EVERGUM AUTO SERVICES				
	Survey held at	EVERGUM AUTO SERVICES BLK 3022A UBI ROAD 1 #01-51	SINGAPORE 408	716		
5a.	Survey held at	BLK 3022A UBI ROAD 1 #01-51	SINGAPORE 408	716		
5a.	A) THE INSPECTION B) THE REPAIRER WAS COMED FOR THE WAS COMED FOR THE WAS COMED FOR THE PAIRER WAS COMED FOR THE WAS COMED FOR THE WAS COMED FOR THE WAS COM	BLK 3022A UBI ROAD 1 #01-51	Remarks THOUT PREJUDI O AT THE TIME O TIMATE. PHOTOGRAPHS	CE" BAS F INSPE	CTION.	
5a.	A) THE INSPECTION B) THE REPAIRER WAS COMED FOR THE WAS COMED FOR THE WAS COMED FOR THE PAIRER WAS COMED FOR THE WAS COMED FOR THE WAS COMED FOR THE WAS COM	BLK 3022A UBI ROAD 1 #01-51 FON WAS CONDUCTED ON A "WISTIMATE WAS NOT PRESENTEI (AS TOLD TO PREPARE THE ESEASE FIND DAMAGED VEHICLE ED REPAIR COST OF THE DAMA	Remarks THOUT PREJUDI O AT THE TIME O TIMATE. PHOTOGRAPHS	CE" BAS F INSPE IN THE I	CTION.	

Report Ref No. CS3/SMO22003033/Uqy3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser