

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22003035/Rvy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 13/04/2022 SINGAPORE 068811 ATTN: KOH JANICE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 5172T** SLZ 9050S Veh. Inspected Policy No. VFX/P2413997 Coverage (\$) 0.00 Claim No. S2M03XAW Excess (\$) 0.00 **KOH JANICE Assign Date** 01/04/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA VIOS E AUTO 1496 Make & Model C.C HIDDEN 2018 Engine No. Year of Reg. MR2B23F3401122918 **GREY** Chassis No. Colour Odometer 138592 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/55 R15 **MARQUIS** 6 mm 195/55 R15 **MARQUIS** L/H Front Tyre 6 mm 195/55 R15 **MARQUIS** R/H Rear Tyre 6 mm **MARQUIS** L/H Rear Tyre 195/55 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 29/03/2022 Inspect Date / Time 04/04/2022 (12:02 PM) Accident Date T & S MOTOR SERVICE Survey held at BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22003035/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

RECO Auto Computer CAE Lineary Association

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

5 Working Days