

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003037/DPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220029022
Claimant Vehicle No :	SJW4477S	Insured Vehicle No :	GBH6587T
Date of Loss:	30/03/2022	Nature of Claim:	TP
		Claim No:	5183865178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW4477S	Engine No:	G4FGGH641704
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MH5720676
Reg. Date:	02/05/2017 (Man. Year: 2017)	Odometer:	263757 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,805.00	5,547.92	11,257.08	66.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	1,390.00	3,200.00	69.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,395.00	6,937.92	14,457.08	67.57
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	21,395.00	5,550.00	15,845.00	74.06
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,917.45		

INSPECTION

Date of Assignment:	01/04/2022	
Date Inspected:	01/04/2022 Inspected At:	Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2 Singapore 569538
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,388.00 F	*1,297.90 FL
2	2		*REAR BOOT HINGER	Not Necessary	148.00 F	*- FL
3	1		*REAR BOOT KIA LOGO	Necessary	37.00 F	*37.00 FL
4	1		*REAR BOOT CERATO K3 EMBLEM	Not fitted	34.00 F	*- FL
5	1		*REAR C&C LOGO	Not fitted	16.00 F	*- FL
6	2		*REAR BOOT LAMP	Mtg Broken	1,160.00 F	*1,160.00 FL
7	2		*REAR BOOT NO.PLATE LAMP	Not Necessary	76.00 F	*- FL
8	1		*REAR BOOT REVERSE CAM	Not Necessary	297.00 F	*- FL
9	2		*REAR BOOT STOPPER	Not Necessary	24.00 F	*- FL
10	1		*REAR BOOT LOCK	Damaged	149.00 F	*149.00 FL
11	1		*REAR BOOT OPENER SWITCH	Not Necessary	69.00 F	*- FL
12	1		*REAR BOOT HANDLE	Not Necessary	38.00 F	*- FL
13	1		*REAR BOOT INNER GARNISH	Not Necessary	221.00 F	*- FL
14	12		*REAR BOOT INNER GARNISH CLIPS	Not Necessary	60.00 F	*- FL
15	2		*REAR LAMP	Mtg Broken	1,278.00 F	*1,278.00 FL
16	2		*REAR LAMP PANEL	Not Necessary	420.00 F	*- FL
17	1		*REAR WEATHERSTRIP	Not Necessary	105.00 F	*- FL
18	1		*REAR SUPPORT PANEL	Repair	347.00 F	*- FL
19	1		*REAR SUPPORT PANEL GARNISH	Mtg Deformed	58.00 F	*58.00 FL
20	1		*REAR SUPPORT PANEL LOCK CATCH	Not Necessary	28.00 F	*- FL
21	1		*REAR SPARE TANK FLOOR PANEL	Not Necessary	714.00 F	*- FL
22	1		*REAR SPARE TANK TOOLS SPONGE	Not Necessary	290.00 F	*- FL
23	1		*REAR SPARE TANK INSULATOR	Not Necessary	280.00 F	*- FL
24	1		*REAR SPARE TANK DUST GARNISH	Not Necessary	49.00 F	*- FL
25	6		*REAR SPARE TANK DUST GARNISH CLIPS	Not Necessary	30.00 F	*- FL
26	1		*REAR SPARE TYRE COVER	Not Necessary	280.00 F	*- FL
27	1		*WINDSCREEN MOULDING	Not Necessary	45.00 F	*- FL
28	1		*WINDSCREEN SEAL	Not Necessary	28.00 F	*- FL
29	1		*WINDSCREEN SEALANT	Not Necessary	120.00 F	*- FL
30	2		*REAR FENDER	Not Necessary	2,448.00 F	*- FL
31	10		*REAR FENDER DUST GARNISH CLIPS	Not Necessary	50.00 F	*- FL
32	2		*REAR FENDER INNER GARNISH TRIM	Not Necessary	362.00 F	*- FL
33	20		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	100.00 F	*- FL
34	1		*REAR FENDER AIR DUCT (RH)	Not Necessary	128.00 F	*- FL
35	1		*REAR BUMPER	Distorted	737.00 F	*737.00 FL
36	1		*REAR BUMPER SPONGE	Not fitted	299.00 F	*- FL
37	1		*REAR BUMPER REINFORCEMENT	Cracked	346.00 F	*346.00 FL
38	4		*REAR BUMPER LOWER BRACKET	Serviceable	128.00 F	*- FL
39	1		*SET REAR BUMPER PARKING SENSOR	Damaged	380.00 FS	*220.00 FS
40	1		*REAR BUMPER SPOILER	Distorted / Deformed	1,050.00 F	*347.90 FL
41	2		*REAR BUMPER REFLECTOR	Not Necessary	264.00 F	*- FL
42	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*REAR EXHAUST	Not Necessary	591.00 F	*- FL
44	4		*REAR EXHAUST MOUNTING	Not Necessary	96.00 F	*- FL
45	1		*REAR EXHAUST CENTRE PIPE	Not Necessary	661.00 F	*- FL
46	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD	Not Necessary	141.00 F	*- FL
47	1		*SET REAR TOUGH COAT SHIELD	Not Necessary	400.00 F	*- FL
48	1		*REAR NO PLATE & BOX	Not Necessary	50.00 F	*- FL
49	1		*REAR BIG BRACKET	O/S Broken / N/S Not Necessary	196.00 F	*98.00 FL
50	1		*SET REVERSE CAMERA	Damaged	390.00 FS	*350.00 FS
51	1		*REVERSE CAMERA HARNESS WIRE	Not Necessary	149.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **16,805.00** **6,098.80**
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 550.88

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						16,805.00 5,547.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING ,REMOVE & REFIT & CHECK SRS ,ABS SENSOR HEAD LAMP SENSOR ,ROOM TAIL LAMP & RESETTING & ERASE FAULT CODE	New	480.00	40.00
2	TO REMOVE & REFIT WINDSCREEN	New	180.00	0.00
3	TO REMOVE & REFIT INTERIOR GARNISH ,CARPET ,CUSHION & ALL ACCIDENT AFFECTED AREA	New	280.00	80.00
4	TO REMOVE & REFIT EXHAUST PIPE ,BOX & ALL AFFECTED AREA	New	220.00	0.00
5	TO REMOVE & REFIT REAR UNDERCARRIAGE & AFFECTED DAMAGE AREA	New	400.00	0.00
6	TO WELDING ,KNOCKING ,STRAIGHTEN REPAIR & RENEW ALL ACCIDENT DAMAGED AFFECTED AREA	New	1,200.00	600.00
7	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA (FRONT/REAR) (PEARL)	New	1,400.00	600.00
8	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	250.00	40.00
9	TO REMOVE & RENEW REVERSE CAMERA & HARNESS WIRE	New	180.00	30.00
Gross Labour Cost (\$\$)			4,590.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >