

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22003043/UEA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SMC4137T **Insured Vehicle No :** SLP4385L
 Date of Loss: 25/03/2022 Nature of Claim: TP Claim No: MFL2022D0001540

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC4137T**
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2A00740
 Reg. Date: 29/06/2018 (Man. Year: 2018) Chassis No: ZYX102125088
 Colour: Grey Odometer: 89675 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: INTERTRAC 7 mm Rear Left Side: INTERTRAC 7 mm
 Front Right Side: INTERTRAC 7 mm Rear Right Side: INTERTRAC 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,866.97	18,383.55	7,483.42	28.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	4,080.00	1,170.00	22.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,116.97	22,463.55	8,653.42	27.81
Approved Total (Overridden) (S\$)		17,800.00		
(S\$)	31,116.97	17,800.00	13,316.97	42.80
+ GST 7.00/7.00% (S\$)	2,178.19	1,246.00	932.19	42.80
Nett Amount (S\$)	33,295.16	19,046.00	14,249.16	42.80
+ Loss of Use (13.0 x S\$80.00/day) (S\$)		1,040.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		20,122.45		
Global Sum Settlement (S\$)		19,800.00		

INSPECTION

Date of Assignment: 01/04/2022
 Date Inspected: 01/04/2022 Inspected At: Focus Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #02-48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 13.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)**Parts:** M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMC4137T)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Buckled	1,806.20 FL	*1,213.10 FL
2	1	*FRONT BONNET LOCK	Bent	124.10 FL	*124.10 FL
3	2	*FRONT BONNET HINGE	Bent / Twisted	130.80 FL	*130.80 FL
4	1	*FRONT BONNET INSULATOR	Warped	313.40 FL	*313.40 FL
5	10	*FRONT BONNET INSULATOR CLIP	Necessary	129.00 FL	*129.00 FL
6	1	*FRONT CENTRE BRACE	Cracked	129.50 FL	*129.50 FL
7	1	*FRONT SUPPORT PANEL	Bent	819.40 FL	*819.40 FL
8	1	*FRONT SUPPORT PANEL TOP GARNISH	Distorted	329.50 FL	*255.10 FL
9	6	*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	67.80 FL	*- FL
10	2	*FRONT HEADLAMP	Holder Cracked	4,290.80 FL	*3,854.00 FL
11	1	*FRONT GRILLE	Cracked	245.10 FL	*245.10 FL
12	1	*FRONT GRILLE GARNISH	Cracked	345.10 FL	*345.10 FL
13	1	*FRONT GRILLE CENTRE EMBLEM	Cracked	1,062.40 FL	*867.40 FL
14	1	*FRONT GRILLE TOP RUBBER	Not Necessary	110.40 FL	*- FL
15	1	*FRONT HOUSING SUPPORT BEAM -RH	Bent	240.10 FL	*155.00 FL
16	1	*FRONT HOUSING SUPPORT BEAM -LH	Bent	240.10 FL	*155.00 FL
17	1	*FRONT BUMPER	Distorted	880.40 FL	*545.10 FL
18	1	*FRONT BUMPER INNER TOP BEAM	Bent	239.40 FL	*239.40 FL
19	1	*FRONT BUMPER TOP INNER AIR DUCT	Distorted	110.40 FL	*110.40 FL
20	1	*FRONT BUMPER REINFORCEMENT	Bent	399.40 FL	*399.40 FL
21	1	*FRONT BUMPER INNER SPONGE	Torn	110.40 FL	*110.40 FL
22	1	*FRONT BUMPER CENTRE GRILLE	Deformed / Torn	405.10 FL	*353.10 FL
23	2	*FRONT BUMPER REINFORCEMENT BRACKET	Bent	248.20 FL	*248.20 FL
24	1	*FRONT BUMPER SIDE COVER-RH	Missing	110.40 FL	*110.40 FL
25	2	*FRONT BUMPER SIDE RETAINER	Bent	220.60 FL	*196.00 FL
26	1	*FRONT NUMBER PLATE SUPPORT	Deformed	124.40 FL	*124.40 FL
27	1	*FRONT FENDER-RH	Repair	727.40 FL	*- FL
28	1	*FRONT FENDER PROTECTOR -RH	Not Necessary	201.10 FL	*- FL
29	1	*FRONT FENDER EMBLEM -RH	Not Necessary	45.90 FL	*- FL
30	1	*FRONT AIR CLEANER BOX	Cracked	809.40 FL	*809.40 FL
31	1	*FRONT AIR CLEANER AIR DUCT	Twisted	140.20 FL	*140.20 FL
32	1	*FRONT AIR CLEANER AIR DUCT PANEL	Distorted	160.40 FL	*160.40 FL
33	1	*FRONT AIR-CON CONDENSER	Bent / Punctured	1,204.10 FL	*1,204.10 FL
34	1	*FRONT AIR-CON AIR SENSOR	Cracked	303.40 FL	*303.40 FL
35	1	*FRONT AIR-CON CONDENSER SIDE GARNISH -RH	Distorted	124.40 FL	*124.40 FL
36	1	*FRONT AIR-CON CONDENSER SIDE GARNISH -LH	Not Necessary	124.40 FL	*- FL
37	1	*FRONT HEADLAMP HIV BULB SENSOR -RH	Not Necessary	403.10 FL	*- FL
38	1	*FRONT AIR-CON FAN COWLING	Cracked	212.40 FL	*212.40 FL
39	1	*FRONT AIR-CON FAN BLADE	Not Necessary	163.40 FL	*- FL
40	1	*FRONT AIR-CON FAN MOTOR	Not Necessary	399.40 FL	*- FL
41	1	*FRONT RADIATOR	Bent / Twisted	1,440.40 FL	*1,440.40 FL
42	1	*FRONT RADIATOR FAN COWLING	Not Necessary	212.40 FL	*- FL
43	1	*FRONT RADIATOR FAN BLADE	Not Necessary	163.40 FL	*- FL
44	1	*FRONT RADIATOR FAN MOTOR	Not Necessary	399.40 FL	*- FL
45	1	*FRONT RADIATOR SPARE TANK -RH	Not Necessary	243.10 FL	*- FL
46	1	*FRONT RADIATOR SPARE TANK TOP HOSE -RH	Not Necessary	69.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BOOT	Repair	1,806.20 FL	*- FL
48	1		*REAR BOOT LOCK	Dented / Shorted	509.40 FL	*509.40 FL
49	1		*REAR BOOT LOCK CATCH	Not Necessary	65.90 FL	*- FL
50	2		*REAR BOOT S/ABSORBER	Not Necessary	798.80 FL	*- FL
51	1		*REAR BOOT RUBBER	Twisted	398.40 FL	*299.10 FL
52	1		*REAR BOOT INNER COVER BOARD	Not Necessary	780.10 FL	*- FL
53	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	866.40 FL	*866.40 FL
54	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Warped	310.40 FL	*310.40 FL
55	1		*REAR SPARE TYRE CENTRE TOOL SPONGE	Torn	544.10 FL	*544.10 FL
56	2		*REAR SPARE TYRE SIDE TRAY SPONGE	Torn	420.80 FL	*420.80 FL
57	2		*REAR FENDER INNER SIDE GARNISH	Deformed / Torn	1,424.20 FL	*1,424.20 FL
58	1		*REAR END PANEL	Badly Dented	517.90 FL	*517.90 FL
59	1		*REAR END PANEL TOP GARNISH	Distorted	349.10 FL	*349.10 FL
60	1		*REAR BUMPER	Distorted	686.40 FL	*545.10 FL
61	2		*REAR BUMPER REFLECTOR COVER	Cut	220.40 FL	*220.40 FL
62	2		*REAR BUMPER SIDE RETAINER	Bent	206.20 FL	*206.20 FL
63	1		*REAR BUMPER LOWER PAD	Distorted	545.10 FL	*343.10 FL
64	1		*REAR BUMPER REINFORCEMENT	Distorted	394.70 FL	*394.70 FL
65	6		*REAR BUMPER LOWER PAD LOCK CLIP	Not Necessary	77.40 FL	*- FL
66	1		*REAR BUMPER TOWING COVER	Torn	66.30 FL	*45.00 FL
67	1		*REAR BUMPER SIDE UNDER COVER -LH	Not Necessary	110.20 FL	*- FL
68	1		*REAR BUMPER SIDE UNDER COVER -RH	Not Necessary	110.20 FL	*- FL
69	10		*REAR BUMPER LOWER CLIP	Necessary	129.00 FL	*129.00 FL
70	1		*REAR EXHAUST SILENCER	Dented / Twisted	1,020.80 FL	*1,020.80 FL
71	2		*REAR EXHAUST SILENCER MOUNTING	Not Necessary	92.40 FL	*- FL
72	1		*REAR EXHAUST SILENCER TOP COVER ALUMINIUM PLATE	Bent	394.10 FL	*290.00 FL
73	1		*REAR SMART SENSOR	Cracked	304.90 FL	*188.20 FL
74	1		*FRONT NUMBER PLATE	Broken	40.00 FS	*40.00 FS
75	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
76	1		*REAR WINDSCREEN GUM	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	34,349.30	24,431.40
- List Item Discount on L Items 25.00/25.00% (\$)	8,482.33	6,047.85
Total Parts (\$)	25,866.97	18,383.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	2,000.00
2	CHECK WIRING AND DIAGNOSIS CHECK	New	250.00	50.00
3	RUST PROOFING	New	160.00	100.00
4	TO REMOVE & REFIX REAR WINDSCREEN	New	160.00	0.00
5	TO REMOVE & REPLACE AIR-CON CONDENSER AND CHARGE GAS	New	160.00	100.00
6	TO REMOVE & REFIX REAR SEAL AND UP-HOLE SET UP	New	160.00	100.00
7	TO REMOVE & REPLACE REAR EXHAUST	New	80.00	80.00
8	TO REMOVE & REPLACE REAR BUMPER SENSOR	New	80.00	50.00
9	TO SPRAY PAINTING	New	1,600.00	1,600.00
			Gross Labour Cost (S\$)	4,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >