

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2204431

300 BEACH ROAD INV Date 20/07/2022

#17-04/07 THE CONCOURSE Reference CC4/LPC22003048/Kea3q2 SINGAPORE 199555

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLH 5529A

Insured Veh. SGV 5067B

Claim No. 21/22/22/VP05/025610

Policy No. Z21VP05029377

Accident Date 30/03/2022

Inspection Date 01/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD		Ref:	CC4/LPC22003048/Kea3q2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	20/07/2022	
				Code:	LPC2	
1.		Policy Particulars	:- THIRD PART	Y CLAIN		
	Insured Veh.	SGV 5067B	Veh. Inspected	d	SLH 5529A	
	Policy No.	Z21VP05029377	Coverage (\$)		0.00	
	Claim No.	21/22/22/VP05/025610	Excess (\$)		0.00	
	Assign From	ENG HUEY NI	Assign Date		31/03/2022	
2.		Vehicle Partic	culars & Condit	ion		
	Make & Model	HONDA HRV (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JHMRU1810GX201194	Colour		METALLIC PEARL WHITE	
	Odometer	70360 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	MICHELIN		8 mm	
	L/H Front Tyre	215/60 R16	MICHELIN		8 mm	
	R/H Rear Tyre	215/60 R16	MICHELIN		8 mm	
	L/H Rear Tyre	215/60 R16	MICHELIN		8 mm	
4.		Description	on of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.			
	DAMAGES SEE DI	ETAILS.				
5.		General	Information			
	Accident Date	30/03/2022	Inspection Date	te	01/04/2022	
	Survey held at	AH LIM MOTOR COMPANY				
		NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047				
5a.		Re	emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate	Days of Repair			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	
	<u> </u>					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5529A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET REAR WINDSCREEN MOULDING	NECESSARY	128.40	128.40
1	TAILGATE	BENT	741.20	741.20
1	TAILGATE LOGO HR-V	NECESSARY	43.20	43.20
1	TAILGATE LOGO I-VTEC	NECESSARY	29.40	29.40
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	96.60	-
1	TAILGATE LOCK CATCH	TO REPAIR SEE LABOUR	36.20	-
1	TAILGATE RUBBER	SERVICEABLE	96.80	-
1	REAR BUMPER (GLOSSY)	BUCKLED	829.40	829.40
8	REAR BUMPER CLIPS	NECESSARY	28.00	28.00
1	REAR SMART BUZZER	SERVICEABLE	80.10	-
1	REAR KEYLESS ANTENNA	SERVICEABLE	58.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	538.20	-
1	REAR END PANEL GARNISH	SERVICEABLE	66.60	-
1	REAR FLOOR UNDERCOVER	SERVICEABLE	190.20	-
	LESS 20% DISCOUNT		-592.48	-359.92
			2,369.92	1,439.68
	SPECIAL NETT ITEMS			
1	PARKING SENSOR 4-IN-1 SET (SN)	SHORTED	400.00	320.00
1	NUMBER PLATE (SN)	SERVICEABLE	35.00	-
1	INNER SEAL (SN)	NECESSARY	20.00	20.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
			495.00	380.00
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	15.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00

Report Ref No. CC4/LPC22003048/Kea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,150.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		60.00	60.00
	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		60.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		60.00	30.00
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL,INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,TAILGATE LOCK CATCH AND REAR END PANEL.		700.00	400.00
	TO SPRAY TAILGATE,REAR END PANE,SPARE TYRE PANEL.		600.00	220.00
			1,640.00	895.00
	GRAND TOTAL		4,504.92	2,714.68

Report Ref No. CC4/LPC22003048/Kea3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 5529A

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLH 5529A

RE-INSPECTION







