

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Xiao Tony

GDH2011008246

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : GBH6085A
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 25.03.2022
TIME OF ACCIDENT : 08:40HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,054.00	\$ 2,054.00 <i>1855.</i>
2	TAILGATE STOPPER <i>new</i>	2	\$ 25.00	\$ 50.00 <i>+</i>
3	TAILGATE DAMPER <i>new</i>	2	\$ 58.00	\$ 116.00 <i>></i>
4	TAILGATE OUTER MOULDING <i>new</i>	1	\$ 464.00	\$ 464.00 <i>x</i>
5	TAILGATE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00 <i>-</i>
6	TAILGATE LOCK MOTOR <i>new</i>	1	\$ 545.00	\$ 545.00 <i>+</i>
7	TAILGATE WEATHERSTRIP <i>lit</i>	1	\$ 410.00	\$ 410.00 <i>355</i>
8	TAILGATE WEATHERSTRIP PROTECTOR <i>Best</i>	1	\$ 485.00	\$ 485.00 <i>198.</i>
9	TAILGATE INNER LOCK <i>damd</i>	1	\$ 285.00	\$ 285.00 <i>✓</i>
10	TAILGATE LOWER LOCK <i>new</i>	1	\$ 45.00	\$ 45.00 <i>x.</i>
11	TAILGATE INNER TRIM <i>new</i>	1	\$ 286.00	\$ 286.00 <i>+</i>
12	TAIL LAMP <i>LH cracked</i>	2	\$ 380.00	\$ 760.00 <i>380.</i>
13	TAILLAMP LOWER GARNISH <i>LH dented</i>	2	\$ 186.00	\$ 372.00 <i>186.</i>
14	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00 <i>+</i>
15	REAR BUMPER <i>dented</i>	1	\$ 479.00	\$ 479.00 <i>-</i>
16	REAR STEP PANEL <i>Dented</i>	1	\$ 386.00	\$ 386.00 <i>-</i>
17	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00 <i>-</i>
18	REAR END PANEL (INNER) <i>Regr</i>	1	\$ 871.00	\$ 871.00 <i>+</i>
19	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 647.00	\$ 647.00 <i>✓</i>
20	REAR END PANEL (EXTEND) RH <i>Dented</i>	1	\$ 186.40	\$ 349.10 <i>186.40</i>
21	REAR FLOOR PANEL <i>3MP</i>	1	\$ 1,960.00	\$ 1,960.00 <i>+</i>
22	REAR FLOOR MATT <i>new</i>	1	\$ 1,050.00	\$ 1,050.00 <i>x.</i>
23	REAR SPARE TYRE HOLDER BRACKET <i>3MP Best</i>	1	\$ 380.00	\$ 380.00 <i>✓</i>
24	REAR SPARE TYRE HOLDER BOLT <i>3MP Best</i>	1	\$ 60.00	\$ 60.00 <i>✓</i>

5507.40.

4130.55

TOTAL PRICE \$ 12,374.10
LESS 25% \$ 3,093.53
SUB TOTAL PRICE \$ 9,280.58

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH6085A
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 25.03.2022
 TIME OF ACCIDENT : 08:40HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Ne n</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	REAR BUMPER CLIP (SET) <i>Nu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	REAR STEP PANEL SEALANT <i>Nu</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
4	TAIL LAMP CLIP (SET) <i>Nu</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
5	TAILLAMP LOWER GARNISH CLIP (SET) <i>Nu</i>	1	\$ 60.00	\$ 60.00 <i>10</i>
6	TAILGATE SEALANT <i>Ne n</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
7	TAILGATE OUTER MOULDING CLIP (SET) <i>Nu</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
8	TAILGATE INNER TRIM CLIP (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
9	TAILGATE STICKER '70KM/H' <i>Nu</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
10	TAILGATE COMPANY STICKER <i>Nec</i>	1	\$ 1,800.00	\$ 1,800.00 <i>750</i>
11	TAILGATE WINDSCREEN SEALANT <i>Nu</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
12	TAILGATE WINDSCREEN INNER SEAL <i>Nu</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
13	REAR END PANEL (INNER) SEALANT <i>Ne n</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
14	REAR END PANEL (OUTER) SEALANT <i>Nec</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
15	REAR FLOOR PANEL SEALANT <i>Ne n</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
16	REAR FLOOR TOP BOARD (WOODEN) (SPECIAL TYPE) <i>Nu</i>	1	\$ 850.00	\$ 850.00 <i>+</i>
17	REAR FLOOR CARPET (SPECIAL TYPE) <i>Nu</i>	1	\$ 680.00	\$ 680.00 <i>+</i>
18	REVERSE CAMERA <i>Nu</i>	1	\$ 550.00	\$ 550.00 <i>+</i>
19	REVERSE SENSOR <i>Dang d</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

TOTAL \$ 5,360.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>700</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	<i>✓</i>
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>+</i>
6	REAR CHASSIS ALIGHMENT	\$ 250.00	<i>+</i>
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>
8	REMOVE AND REFIX REAR REVERSE CEMERA	\$ 80.00	<i>50</i>

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : GBH6085A
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 25.03.2022
TIME OF ACCIDENT : 08:40HRS

9	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	✓
10	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 80.00	x
11	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1830

TOTAL

4850

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,640.58
TOTAL LABOUR COST : \$ 4,850.00
TOTAL REPAIR COST : \$ 19,490.58

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian Li
r/s 06/04/22.
06 days.

total: 7125.55
r/s: 5.7K

5.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: