

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22003052/DVY3E2

Date: 12/07/2022

REFERENCE

Insured/Claimant:	CHEN WENXIONG	Policy No:	MP316228		
Date of Loss:	30/03/2022	Nature of Claim:	OD	Claim No:	MPC03278/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX4050Z		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B6022382
Reg. Date:	11/01/2021 (Man. Year: 2019)	Chassis No:	GK82102048
Colour:	Black	Odometer:	19477 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,814.00	2,383.50	430.50	15.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	600.00	80.00	11.76
Paintwork Labour	880.00	720.00	160.00	18.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,374.00	3,703.50	670.50	15.33
- Excess (\$\$)	0.00	325.00	-325.00	
(\$\$)	4,374.00	3,378.50	995.50	22.76
+ GST 7.00/7.00% (\$\$)	306.18	236.50	69.68	22.76
Nett Amount (\$\$)	4,680.18	3,615.00	1,065.18	22.76

INSPECTION

Date of Assignment:	01/04/2022	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	02/04/2022	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jul 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX4050Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front LH door (WCP)	Buckled	550.00 F	*550.00 F
2	1		*Front LH door outer moulding (WCP)	Necessary	50.00 F	*50.00 F
3	1		*Front LH door outer handle (WCP)	Cut	240.00 F	*240.00 F
4	1		*Front LH door frame pillar sticker (WCP)	Necessary	40.00 F	*40.00 F
5	1		*Front LH door rubber (WCP)	Necessary	30.00 F	*30.00 F
6	1		*Front LH door power window motor with gear (WCP)	Bent	140.00 F	*140.00 F
7	1		*Front LH door inner trimboard (WCP)	Mtg Cracked	380.00 F	*380.00 F
8	1		*Front LH door lock (WCP)	Not Necessary	150.00 F	*- F
9	1		*LH side skirt (WCP)	Cut	250.00 F	*250.00 F
10	1		*LH rocker panel (WCP)	Repair	260.00 F	*- F
11	1		*Rear LH door (WCP)	Buckled	470.00 F	*470.00 F
12	1		*Rear LH door outer moulding (WCP)	Necessary	30.00 F	*30.00 F
13	1		*Rear LH door frame pillar sticker (WCP)	Necessary	20.00 F	*20.00 F
14	1		*Rear LH door rubber (WCP)	Necessary	40.00 F	*40.00 F
15	1		*Rear LH door lower hinge (WCP)	Bent	30.00 F	*30.00 F

F=Franchise part.

Sub Total (\$\$)	2,680.00	2,270.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	134.00	113.50
Total Parts (\$\$)	2,814.00	2,383.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	880.00	720.00
<u>Labour Items</u>				
2	To repair damages	New	680.00	600.00
Gross Labour Cost (S\$)			1,560.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >