

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003054/GPA3Q2**Date:** 18/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210124929
Claimant Vehicle No :	SDX7177D	Insured Vehicle No :	GBL5691K
Date of Loss:	01/04/2022	Nature of Claim:	TP
		Claim No:	0401958981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDX7177D	Engine No:	DEM024262
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF43LN014832
Reg. Date:	30/04/2021 (Man. Year: 2020)	Odometer:	12398 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	245/35Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,709.00	3,821.00	1,888.00	33.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,642.00	1,522.00	4,120.00	73.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,351.00	5,343.00	6,008.00	52.93
+ GST 7.00/7.00% (S\$)	794.57	374.01	420.56	52.93
Nett Amount (S\$)	12,145.57	5,717.01	6,428.56	52.93
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/04/2022	
Date Inspected:	07/04/2022	Inspected At: Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	3,431.00 FS	*3,431.00 FS
2	8		*RIVETTED CAP NUTS	Necessary	28.00 FS	*28.00 FS
3	1		*FRONT DOOR OUTER DOOR SEAL LH	Necessary	229.00 FS	*229.00 FS
4	1		*BONDING AGENT	Necessary	51.00 FS	*51.00 FS
5	1		*CLEANING SOLUTION	Necessary	74.00 FS	*74.00 FS
6	1		*APPLICATOR	Necessary	8.00 FS	*8.00 FS
7	1		*FRONT DOOR CATCH	Not Necessary	116.00 FS	*- FS
8	1		*FRONT DOOR ATTACHMENTS PARTS	Not Necessary	1,153.00 FS	*- FS
9	1		*SILL TRIM STRIP LH	Not Necessary	133.00 FS	*- FS
10	6		*FRONT DOOR CLIPS	Not Necessary	6.00 FS	*- FS
11	1		*STONECHIPS	Not Necessary	180.00 FS	*- FS
12	1		*SUNDRIES	*Check	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	5,709.00 3,821.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES	New	350.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR .TO REPAIR LHS FRONT FENDER AND LHS SILL PANEL .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY LHS FRONT FENDER ,LHS FRONT DOOR AND LHS SILL PANEL	New	3,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,642.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >