

SLMS2836 . 2017 March.

Mazda 3 1496 cc

TP Chim
Ceilia.

JMGBN22A8H0145968

Rear Bumper Deformed 1028 ✓

Rear Bumper Clips. ^{new} 30(SN) ✓

Rear Bumper Side Holder x 02 ^{new} 38 x 2 = 76. x

Rear Bumper Tow Cover x 02 ^{AP} 18 x 2 = 36 x

Rear Bumper Reinforcement Dented 498.60 ✓

Rear Bumper Reflector x 02 ^{AP} 53 x 2 = 106. X

Reverse Sensor Damaged 280(~~SN~~) 200(SN)
1526.60 S.N: 230
1221.28

Panel Beating ~~400~~ 200
Spray Painting. ~~400~~ 200 480.

Wiring. ~~50~~ 30

To remove reverse sensor ~~100~~ 50

Total: 1931.28
CPIP)
03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: