

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003059/KPA3Q2**Date:** 29/12/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100490373
Claimant Vehicle No :	SKV5426B	Insured Vehicle No :	SLH7521H
Date of Loss:	30/03/2022	Nature of Claim:	TP
		Claim No:	1209388054SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV5426B		
Make & Model:	MITSUBISHI OUTLANDER, 2.4G (A)	Engine No:	4B12PY6723
Reg. Date:	23/09/2015 (Man. Year: 2015)	Chassis No:	JMYXTGF3WGW001164
Colour:	Metallic Red	Odometer:	236976 km
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,481.20	3,303.00	178.20	5.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,165.00	940.00	225.00	19.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,646.20	4,243.00	403.20	8.68
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	4,646.20	3,350.00	1,296.20	27.90
+ GST 7.00/7.00% (S\$)	325.23	234.50	90.73	27.90
Nett Amount (S\$)	4,971.43	3,584.50	1,386.93	27.90
+ Car Rental (6.0 x S\$160.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,546.50		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment:	01/04/2022		
Date Inspected:	01/04/2022	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Buckled	855.00 FL	*855.00 FL
2	1		*FRONT O/S BUMPER ARCH GARNISH	Dented / Cut	104.00 FL	*104.00 FL
3	1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	16.00 FL	*16.00 FL
4	1		*FRONT O/S FOGLAMP COVER	Cut	71.00 FL	*71.00 FL
5	1		*FRONT O/S BUMPER OUTER CHROME	Serviceable	198.00 FL	*- FL
6	1		*FRONT O/S SPORT RIM	Dented	1,152.00 FL	*1,152.00 FL
7	1		*FRONT O/S KNUCKLE ARM	Bent	332.00 FL	*332.00 FL
8	1		*FRONT O/S KNUCKLE BEARING HUP	Bent	204.00 FL	*204.00 FL
9	1		*FRONT O/S WHEEL BEARING	Necessary	143.00 FL	*143.00 FL
10	1		*FRONT O/S LOWER ARM	Distorted	333.00 FL	*333.00 FL
11	1		*FRONT O/S SHOCK ABSORBER	Bent	460.00 FL	*460.00 FL
					Sub Total (\$\$)	3,868.00 3,670.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	386.80 367.00
					Total Parts (\$\$)	3,481.20 3,303.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	200.00	180.00
2	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	500.00	400.00
4	TO REMOVE ,CUT-OUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ABOVE PARTS	New	400.00	300.00
Gross Labour Cost (\$\$)			1,165.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >