

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1684J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER (WCP)	CRACKED	370.00	370.00
1	RH BUMPER BRACKET (WCP)	BENT	90.00	90.00
1	RADIATOR GRILLE (WCP)	CRACKED	300.00	300.00
1	RADIATOR GRILLE BASE (NPA) (WCP)	SERVICEABLE	-	-
1	FRT CENTER PANEL (WCP)	BENT	500.00	500.00
1	FRT CENTER PANEL RUBBER SEAL (WCP)	NECESSARY	30.00	30.00
1	ISUZU EMBLEM (WCP)	NECESSARY	95.00	95.00
1	RH LOWER STEP GARNISH (WCP)	DENTED	95.00	95.00
1	AIR CON BLOWER MOTOR ASSY (WCP)	SERVICEABLE	360.00	-
1	AIR CON COOLING COIL ASSY (WCP)	SERVICEABLE	1,300.00	-
	COST PLUS 10%		314.00	-
	COST PLUS 5%		-	74.00
			3,454.00	1,554.00
	SPECIAL NETT ITEMS			
1	FRT 100 PLUS STICKER(BUMPER,CTR PANEL, GRILLE) (INSURED) (SN)	NECESSARY	700.00	500.00
			700.00	500.00
	<u>LABOUR</u>			
	TO CUT, WELD FRT PANEL, PANEL BEAT ON FRT AFFECTED AREAS, REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS.		1,200.00	700.00
	TO PUTTY, RESPRAY FRT PANEL, BUMPER AND AFFECTED AREAS.		1,200.00	600.00
	TO CHECK LIGHTING AND WIRING.		30.00	20.00
	REMOVE DASHBOARD TO ASSIST REPAIR AND REIFT.		200.00	200.00
	REMOVE AIR CON BLOWER AND COOLING COIL TO ASSIT REPAIR AND REPLACE.		100.00	100.00
	TO REMOVE FRT WINDSCREEN GLASS TO ASSIST REPAIR AND REFIT.		120.00	120.00
			2,850.00	1,740.00
	GRAND TOTAL		7,004.00	3,794.00

Report Ref No. CS/AWA22003064/Kny3m4



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		3,794.00
LESS EXCESS		-1,500.00
NETT LIABILITY		2,294.00

Report Ref No. CS/AWA22003064/Kny3m4

KONG SENG CHEONG

Licensed Appraiser