



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1672D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER-RR BUMPER	CUT	459.40	459.40
1	MOULDING ASSY-RR BUMPER C	SCRATCHED	451.25	451.25
1	MOULDING-REAR BUMPER LWR	SERVICEABLE	155.00	-
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	BUMPER TOW COVER	SERVICEABLE	98.80	-
	LESS 20% DISCOUNT		-237.29	-186.53
			949.16	746.12
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR ASSY (SN)	SERVICEABLE	180.00	-
1	PROTECTOR MAT (SN)	SERVICEABLE	50.00	-
2	REAR FENDER ADV.STCIKER RH / LH (SN)	NECESSARY	200.00	200.00
			430.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,199.16	1,576.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/GAI22003072/Vty3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.