

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22003075/Gvy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	13/04/2022		
	ATTN: TEO KITTY			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLR 6137M	Veh. Inspected	t	SLL 7988Z	
	Policy No.	P2415936	Coverage (\$)		0.00	
	Claim No.	S2M03XKM	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		04/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ B 160	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WDD2452312J735552	Colour		BLUE	
	Odometer	164880 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45Z R17	PETLAS		6 mm	
	L/H Front Tyre	215/45Z R17	PETLAS		6 mm	
	R/H Rear Tyre	215/45Z R17	PETLAS		6 mm	
	L/H Rear Tyre	215/45Z R17	PETLAS		6 mm	
4.	I. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	01/04/2022	Inspect Date /	Time	04/04/2022 ( 03:00 PM )	
	Survey held at	SPEEDWERKZ PTE LTD		_		
		13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/ASM22003075/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**