

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003078/AEA3Q2**Date:** 23/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800111118
Claimant Vehicle No :	SFH2332R	Insured Vehicle No :	SGZ240D
Date of Loss:	31/03/2022	Nature of Claim:	TP
		Claim No:	3513299775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFH2332R	Engine No:	L15B6021472
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82101256
Reg. Date:	28/02/2020 (Man. Year: 2019)	Odometer:	87124 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,644.00	3,823.36	5,820.64	60.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	930.00	3,670.00	79.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,244.00	4,753.36	9,490.64	66.63
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	14,244.00	3,800.00	10,444.00	73.32
+ GST 7.00/7.00% (S\$)	997.08	266.00	731.08	73.32
Nett Amount (S\$)	15,241.08	4,066.00	11,175.08	73.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	04/04/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	12/04/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,150.00 FL	*1,150.00 FL
2	2		*FRONT BONNET HINGE	Not Necessary	126.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	215.20 FL	*- FL
4	1		*FRONT BONNET HOUSING	Not Necessary	80.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	1,250.00 FL	*1,250.00 FL
6	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	110.40 FL	*55.20 FL
7	1		*FRONT BUMPER TOWING COVER	Not Necessary	50.00 FL	*- FL
8	1		*FRONT BUMPER FOGLAMP UPPER GARNISH	N/S Missing	105.20 FL	*52.60 FL
9	1		*FRONT BUMPER FOGLAMP LOWER GARNISH	N/S Missing	145.00 FL	*72.50 FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	188.50 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	420.90 FL	*420.90 FL
12	1		*FRONT BUMPER UNDER PANEL	Not Necessary	255.60 FL	*- FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	190.00 FL	*- FL
14	1		*FRONT CENTRE GRILLE	Not Necessary	395.00 FL	*- FL
15	1		*FRONT CENTRE GRILLE LOGO	Necessary	60.00 FL	*60.00 FL
16	1		*FRONT CENTRE GRILLE LOGO CHROME	Cracked	350.00 FL	*350.00 FL
17	1		*FRONT CENTRE GRILLE LOWER CHROME	Not Necessary	280.00 FL	*- FL
18	1		*FRONT HEAD LAMP	N/S Cracked	2,511.00 FL	*1,255.50 FL
19	2		*FRONT HEADLAMP TOP BRACKET	Not Necessary	125.00 FL	*- FL
20	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	110.80 FL	*- FL
21	2		*FRONT FENDER	Not Necessary	1,428.00 FL	*- FL
22	2		*FRONT FENDER INNER TRIM	Not Necessary	1,160.00 FL	*- FL
23	1		*FRONT SUPPORT PANEL	Not Necessary	855.90 FL	*- FL
24	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	160.00 FL	*- FL
25	2		*FRONT SUPPORT PANEL SIDE GARNISH	Not Necessary	145.00 FL	*- FL
26	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
27	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
28	1		*SET FRONT BUMPER UNDER COVER CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*SET FRONT CENTRE GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
30	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
31	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,017.50	4,756.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,373.50	933.34
Total Parts (\$\$)	9,644.00	3,823.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	2,000.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	400.00
3	TO ADJUST AND REFOCUS HEADLAMP	New	200.00	0.00
4	TUFF COAT	New	200.00	0.00
5	WIRING CHECK	New	200.00	30.00
Gross Labour Cost (\$)			4,600.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >