

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122003079/VVY3N2**Date:** 13/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SHA2990D **Insured Vehicle No :** SMD2598D  
 Date of Loss: 01/04/2022 Nature of Claim: TP Claim No: CDMPG22000578

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2990D**  
 Make & Model: HYUNDAI IONIQ EV FL SR, 1.6 (A) Engine No: G4LEKU295297  
 Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164326  
 Colour: Blue Odometer: 230699 km  
 Engine Capacity: 1580 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm  
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	999.49	999.49	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	620.00	130.00	17.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,749.49</b>	<b>1,619.49</b>	<b>130.00</b>	<b>7.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	122.46	113.36	9.10	7.43
<b>Nett Amount (S\$)</b>	<b>1,871.95</b>	<b>1,732.85</b>	<b>139.10</b>	<b>7.43</b>

INSPECTION

Date of Assignment: 04/04/2022  
 Date Inspected: 04/04/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969  
 Estimated Period of Repair: 2.0 days

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 12 May 2022)**Parts:** 192      HYUNDAI IONIQ EV FL SR 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHA2990D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Cut	459.40 FL	*459.40 FL
2	1		*MOULDING ASSY-RR BUMPER C	Scratched	451.25 FL	*451.25 FL
3	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
4	1		*VEHICLE NUMBER PLATE REAR	Dented	50.00 FS	*50.00 FS
5	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
6	1		*ADVERTISEMENT STICKER	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,232.65</b>	<b>1,232.65</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	233.16	233.16
<b>Total Parts (\$\$)</b>	<b>999.49</b>	<b>999.49</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	20.00
			<b>Gross Labour Cost (\$)</b>	<b>620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >