6/8/22, 1:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22003088/ATY3N2

Date: 08/06/2022

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP316766

Claimant Vehicle CAM 2004

No: SML2384L Insured Vehicle No: SGX6556P

Date of Loss: 20/03/2022 Nature of Claim: TP Claim No: MPC03241/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML2384L

Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: DFY295647

Reg. Date: 09/09/2021 (Man. Year: 2021) Chassis No: WAUZZZGY7NA007054

Colour: Red Odometer: 6718 km

Engine Capacity: 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/40R18 Rear Tyre Size: 215/40R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,323.00	0.00	9,323.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,772.00	2,350.00	45.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,445.00	2,772.00	11,673.00	80.81
+ GST 7.00/7.00% (S\$)	1,011.15	194.04	817.11	80.81
Nett Amount (S\$)	15,456.15	2,966.04	12,490.11	80.81

INSPECTION

Date of Assignment: 05/04/2022

Premium Automobiles Pte Ltd (UBI)

Date Inspected: 25/03/2022 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/8/22, 1:32 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jun 2022)

Parts: 143 AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML2384L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,677.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	290.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	130.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTER	Not Necessary	265.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	67.00 FS	*- FS
6	1		*FRONT BUMPER TRIM COVER-RH	Not Necessary	104.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	171.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE SUPPORT-RH	Not Necessary	43.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	54.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	93.00 FS	*- FS
11	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
12	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
13	1		*FRONT FENDER-RH	Repair	1,241.00 FS	*- FS
14	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	32.00 FS	*- FS
15	3		*FRONT FENDER POP RIVET	Not Necessary	12.00 FS	*- FS
16	1		*FRONT FENDER BRACE-RH	Not Necessary	98.00 FS	*- FS
17	1		*FRONT FENDER BRACKET-RH	Not Necessary	46.00 FS	*- FS
18	1		*FRONT FENDER BRACKET END-RH	Not Necessary	35.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	183.00 FS	*- FS
20	1		*FRONT WHEEL HOUSING LINER CLOSING ELEMENT-RH	Not Necessary	22.00 FS	*- FS
21	1		*HEADLIGHT-RH	Not Necessary	4,084.00 FS	*- FS
22	1		*LIFT CYLINDER-RH	Not Necessary	211.00 FS	*- FS
23	1		*LIFT CYLINDER HOSE	Not Necessary	108.00 FS	*- FS
24	1		*FRONT PARKING AID SENSOR SIDE (NPA)	Not Necessary	0.00 FS	*- FS
25	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	32.00 FS	*- FS
26	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fr	anchise	part. S=Spc	Nett.			
				Total Parts (S\$)	9,323.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	700.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,400.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		5,122.00	2,772.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >