

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____ Com Del

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 20 days Res.: Yes or NoLum Sum: 20 + B.T. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC 386014 Yr Regn: 10, 21Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato c.c. 1591Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 21498 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAP 3416 mm 3107424Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hunko

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 28/3/22

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 1/4/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/4 21Rm & 2750L Carbrim

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SNC3860HMake & Model : CERATO 1.6(A) EXYear of Manufacture : 2021Chassis No. : KNAF3416MM5107424Ins Company : III VS LONPAC

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 3/28/2022Time of Accident : 0915

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimatesParts (a) Cost / List Price Items \$ 3,932.80Plus/Less 10% \$ 393.28Total of Cost / List \$ 3,539.52(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,539.52Labour (Appendix B) \$ 1,130.00Total Repair Cost \$ 4,669.52

Case Owner : _____

Signature : _____

Contact No

Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

Back-end Operation

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

Not Authorised
Resurvey B4 repair

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : SPKSurvey conducted on : 1/4/22 at _____**Remarks By Surveyor**(a) The repair of this vehicle is author / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 1/4/22

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SNC3860H Case Owner : 0

Make & Model : CERATO 1.6(A) EX Year Manufacture : 2021

Chassis No : KNAF3416MM5107424 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BOOTLID <i>12PF</i>	<i>Bj</i> 1		\$ 1,297.00			<i>✓</i>
2	BOOTLID LOGO	<i>M</i> 1		\$ 35.00			<i>✓</i>
3	BOOTLID EMBLEM 'CERATO'	<i>M</i> 1		\$ 32.80			<i>✓</i>
4	BOOTLID LAMP RH	1	<i>Sm</i>	\$ 608.00			<i>X</i>
5	BOOTLID LAMP CENTER <i>690</i>	<i>Scr/lot</i> 1		\$ 690.00			<i>X</i>
6	REAR BUMPER <i>688</i>	<i>Bu</i> 1		\$ 688.00			<i>✓</i>
7	REAR BUMPER SIDE RETAINER LH	<i>Sm</i> 1		\$ 33.00			<i>X</i>
8	REAR BUMPER SIDE RETAINER RH	<i>Sm</i> 1		\$ 33.00			<i>X</i>
9	REAR BUMPER LOWER GARNISH	<i>D</i> 1		\$ 197.00			<i>✓</i>
10	REAR BUMPER REINFORCEMENT	1	<i>R</i>	\$ 319.00			<i>X</i>
11	REAR BUMPER SPONGE	1		NA			
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Case Owner	:	<u>0</u>
Year of Manufacture	:	<u>2021</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.