

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	CS/LPC22003102/Kqy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	18/05/2022	
			Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GZ 5900A	Veh. Inspected	SJQ 5125H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	21/22/22/VC00/025531	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	04/04/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	KMHDU41BR9U761850	Colour	METALLIC BLACK	
	Odometer	373023 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	GOODYEAR	3 mm	
	L/H Front Tyre	195/65 R15	GOODYEAR	3 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/03/2022	Inspection Date	25/04/2022	
	Survey held at KIEN CHEONG MOTOR WORKS				
		BLK 9 SIN MING IND EST SECTOR C #01-26 SINGAPORE 575644			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			