

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22003106/Gqy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	13/04/2022	
	ATTN: ANG YVON	NE		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 1307Z	Veh. Inspected	t	GBF 3565L
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03XM0	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		04/04/2022
2.	Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR 3.0	c.c		2953
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	JN1SC2F24Z0858935	Colour		YELLOW
	Odometer	308414 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15	LAUFENN		6 mm
	L/H Front Tyre	195 R15	LAUFENN		6 mm
	R/H Rear Tyre	165 R13	DELIUM		6 mm
	L/H Rear Tyre	165 R13	DELIUM		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	02/04/2022	Inspect Date /	Time	05/04/2022 ( 04:30 PM )
	Survey held at SHENG LI LAI				
	2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				

Report Ref No. CS3/ASM22003106/Gqy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**