

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003116/UQY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00075282100		
<b>Claimant Vehicle No :</b>	GBH7445M	<b>Insured Vehicle No :</b>	YQ3810Z		
Date of Loss:	01/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202273/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH7445M</b>		Engine No:	YD25034384B
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)		Chassis No:	JN1MC2E26Z0030555
Reg. Date:	19/09/2018 (Man. Year: 2018)		Odometer:	77151 km
Colour:	Grey			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

**CONDITION OF TYRES**

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	KAPSEN 8 mm	Rear Left Side:	KAPSEN 8 mm
Front Right Side:	KAPSEN 8 mm	Rear Right Side:	KAPSEN 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,631.22	6,087.22	6,544.00	51.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,580.00	5,818.00	4,762.00	45.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>23,211.22</b>	<b>11,905.22</b>	<b>11,306.00</b>	<b>48.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,624.79</b>	<b>833.37</b>	<b>791.42</b>	<b>48.71</b>
<b>Nett Amount (S\$)</b>	<b>24,836.01</b>	<b>12,738.59</b>	<b>12,097.42</b>	<b>48.71</b>

**INSPECTION**

Date of Assignment:	05/04/2022		
Date Inspected:	05/04/2022	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	12.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 28 Apr 2022)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH7445M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH RR COMB LAMP	Broken	242.80 FN	*242.80 FN
2	1		*RH RR COMB LAMP	Not Necessary	242.80 FN	*- FN
3	1		*INNER RR END PANEL	Repair	498.10 FN	*- FN
4	1		*LH HEADLAMP	Not Necessary	429.10 FN	*- FN
5	1		*RH HEADLAMP	Cracked	429.10 FN	*429.10 FN
6	1		*EMBLEM-RADIATOR	Not Necessary	86.20 FN	*- FN
7	1		*GRILLE-RADIATOR	Not Necessary	644.70 FN	*- FN
8	1		*LOWER GRILLE FRT BUMPER	Not Necessary	1,016.00 FN	*- FN
9	1		*LH SIDE BRACKET FRT BUMPER	Not Necessary	177.80 FN	*- FN
10	1		*RH SIDE BRACKET FRT BUMPER	Not Necessary	177.80 FN	*- FN
11	1		*FRT BUMPER	Repair	617.70 FN	*- FN
12	1		*FRT CENTER CAR PANEL	Dented	1,326.70 FN	*1,326.70 FN
13	1		*EMBLEM-BACK DOOR NISSAN URVAN NV350	Necessary	118.70 FN	*118.70 FN
14	1		*EMBLEM-REAR NISSAN	Necessary	70.00 FN	*70.00 FN
15	1		*TAIL GATE STRIKER	Not Necessary	37.60 FN	*- FN
16	1		*TAILGATE LOCK	Dented/Jammed	309.70 FN	*309.70 FN
17	1		*TAIL GATE CHROME FINISHER	Cracked	578.30 FN	*578.30 FN
18	1		*GLASS TAIL GATE	Shorted	961.20 FN	*961.20 FN
19	1		*TAILGATE	Badly Dented	1,961.00 FN	*1,961.00 FN
20	1		*LH TAIL LAMP PANEL	Repair	381.00 FN	*- FN
21	1		*LH RR FENDER PANEL (WITHOUT WINDOW PANEL)	Repair	2,169.20 FN	*- FN
22	1		*INNER BRACKET CENTER RR BUMPER	Bent	185.80 FN	*185.80 FN
23	10		*CLIP RR BUMPER	Necessary	14.00 FN	*14.00 FN
24	1		*RR BUMPER	Distorted	720.60 FN	*720.60 FN
25	1		*OUTER END PANEL	Badly Dented	158.80 FS	*158.80 FS
26	1		*70KM/H	Necessary	15.00 FS	*15.00 FS
27	1		*LABEL-PAX 8	Necessary	15.00 FS	*15.00 FS
28	1		*AIRCON BLOWER	Not Necessary	770.10 FS	*- FS
29	1		*SENSOR-REVERSE	Shorted	250.00 FS	*250.00 FS
30	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
31	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
32	1		*LH RR BACK PILLAR REINFORCEMENT	Repair	565.00 FL	*- FL
33	1		*WEATHER STRIP TAILGATE	Not Necessary	145.00 FN	*- FN
34	1		*REAR WIPER ARM CORNER COVER	Missing	14.10 FS	*14.10 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>15,508.90</b>	<b>7,470.80</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$)</b>	169.50	0.00
<b>- Nett Item Discount on N Items 20.00/20.00% (\$)</b>	2,708.18	1,383.58
<b>Total Parts (\$)</b>	<b>12,631.22</b>	<b>6,087.22</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR CHARGES TO REPAIR RH RH RR FENDER TRUNKFLOOR,RENEW INNER/OUTER END PANEL,TAILGATE RR BMPR LH,FENDER PANEL,LH RR TAIL LAMP PANEL,LH RR FENDER INNER PANEL,FRT BUMPER,FRT CENTER CAP PANEL	New	4,600.00	2,800.00
2	CHARGES TO SPRAY PAINTING SAME	New	3,000.00	2,000.00
3	RENEW REAR WINDSCREEN GLASS	New	240.00	180.00
4	APPLY SEALANT TO TAIL GATE AND OUTER END PANEL INNER END PANEL	New	300.00	200.00
5	PERFORM RUSTPROOFING LH RR FENDER,OUTER END PANEL,INNER END PANEL	New	480.00	120.00
6	REMOVE AND TRANSFER TAIL GATE MECHANISM	New	160.00	80.00
7	REMOVE AND INSTALL REVERSE CAMERA }	New	180.00	120.00
8	RENEW REVERSE SENSOR }	New	110.00	0.00
9	REMOVE AND INSTALL BOTH HEADLAMP AND CHECK REPLACE IF NEED TO CHANGE	New	85.00	48.00
10	RENEW AC BLOWER	New	180.00	0.00
11	SUPPLY FRT & RR LICENSE PLATE (NPA)	New	0.00	0.00
12	COMPUTER CHECK DIAGNOSIS	New	180.00	120.00
13	REMOVE AND INSTALL DASHBOARD	New	280.00	0.00
14	TO SUPPLY LH RR FENDER COMPANY STICKER	New	300.00	0.00
15	TO SUPPLY COMPANY STICKER 87382661 64455396 LIDO DRY CLEANING	New	400.00	150.00
16	RENEW BOTH RR COMB LAMP	New	85.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,580.00</b>	<b>5,818.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >