



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3236S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER-RR-BUMPER	DENTED	459.40	459.40
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	MOULDING ASSY-RR BUMPER C	SCRATCHED	451.25	451.25
1	BRACKET ASSY-RR BUMPER SI	NECESSARY	55.80	55.80
1	BEAM-RR BUMPER	SERVICEABLE	394.80	-
1	REFLECTOR/REFLEX ASSY-RR	SCRATCHED	41.45	41.45
1	UNIT ASSY-BSL LH	SERVICEABLE	1,784.40	-
	LESS 20% DISCOUNT		-641.82	-205.98
			2,567.28	823.92
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT CHARGE.		300.00	250.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		50.00	30.00
			800.00	660.00
GRAND TOTAL			3,367.28	1,483.92
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,483.92

Report Ref No. NS/INC22003122/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.