



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 8089A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN	NOT NECESSARY	988.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	165.00	110.00
1	TAILGATE	WARPED / CRACKED	2,867.00	2,667.00
1	TAILGATE OUTER GARNISH	DISTORTED	450.00	366.00
1	TAILGATE CHROME MOULDING	CRACKED	300.00	280.00
1	TAILGATE REAR LOGO	NECESSARY	85.00	85.00
1	TAILGATE 'CITROEN' EMBLEM	NECESSARY	82.00	82.00
1	TAILGATE 'C4' EMBLEM	NECESSARY	60.00	60.00
1	TAILGATE 'SPACETOURER' EMBLEM	NECESSARY	88.00	88.00
1	TAILGATE 'PURETECH' EMBLEM	NECESSARY	68.00	68.00
1	TAILGATE INNER LOCK	TWISTED	188.00	188.00
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	620.00	545.00
1	TAILGATE WEATHERSTRIP	TWISTED	179.00	179.00
2	TAILGATE LAMPS @\$600.00	CRACKED	1,200.00	1,010.00
1	REAR BUMPER TOP	DISTORTED	1,209.00	1,109.00
1	REAR BUMPER LOWER	DISTORTED	820.00	800.00
2	REAR BUMPER LAMPS @\$250.00	N/S CRACKED	500.00	195.00
2	REAR BUMPER LAMP INNER GUIDES @\$180.00	TWISTED / CRACKED	360.00	300.00
4	REAR BUMPER PDC SENSORS @\$180.00	SHORTED (2 PCS ONLY)	720.00	360.00
1	REAR BUMPER PDC SENSOR WIRE	SERVICEABLE	245.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER SKIRTING	DISTORTED	367.00	367.00
1	REAR BUMPER BEAM	DISTORTED	630.00	595.00
1	REAR BUMPER BEAM GARNISH	DISTORTED	450.00	422.00
1	REAR END PANEL OUTER	BADLY DENTED	875.00	785.00
1	REAR END PANEL INNER	BADLY DENTED	800.00	600.00
1	REAR END PANEL TOP GARNISH	TWISTED	366.00	266.00
1	REAR END PANEL ANTENNA SENSOR	CRACKED	190.00	162.00

Report Ref No. CS/AGI22003133/Uvy3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE CARRIER	JAMMED / DAMAGED	366.00	366.00
1	REAR BUZZLE SENSOR	SHORTED	185.00	160.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,290.00	-
1	REAR FLOOR PANEL TOP BOARD	WARPED	655.00	655.00
2	REAR FENDER INNER TRIM BOARDS @\$590.00	NOT NECESSARY	1,180.00	-
	LESS 10% DISCOUNT		-	-1,292.00
			18,598.00	11,628.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR REVERSE CAMERA (SN)	SERVICEABLE	450.00	-
			700.00	220.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		120.00	120.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REPLACED REAR REVERSE CAMERA.		100.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO RESET & DIAGNOSTIC SYSTEM.		180.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	60.00
	LABOUR FOR PANEL BEATING AND REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		1,500.00	850.00
	TO PUTTY AND SPRAY PAINTING.		1,600.00	1,200.00
			4,070.00	2,550.00
	<b>GRAND TOTAL</b>		<b>23,368.00</b>	<b>14,398.00</b>

Report Ref No. CS/AGI22003133/Uvy3n2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>11,500.00</b>
---	--	--	------------------

Report Ref No. CS/AGI22003133/Uvy3n2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**