

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22003134/UTY3N2**Date:** 13/05/2022**REFERENCE**

Insured/Claimant:	SEE CHENG SIM	Policy No:	MPC21P00125200	
Date of Loss:	02/04/2022	Nature of Claim:	OD	Claim No: DMPC2200136H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCR222X		Engine No:	HRA2627444A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT (A)		Chassis No:	SJNFEAJ11U2289377
Reg. Date:	20/06/2018 (Man. Year: 2018)		Odometer:	63192 km
Colour:	Grey			
Engine Capacity:	1197 cc			
Market Value/New Car Price:	S\$78,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,567.00	4,873.00	1,694.00	25.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,270.00	340.00	21.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,177.00	6,143.00	2,034.00	24.87
+ GST 7.00/7.00% (S\$)	572.39	430.01	142.38	24.87
Nett Amount (S\$)	8,749.39	6,573.01	2,176.38	24.87

INSPECTION

Date of Assignment:	05/04/2022	Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	06/04/2022	Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 May 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCR222X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Repair	720.00 F	*- F
2	1		*LH HEADLAMP (WCP)	Cracked	1,950.00 F	*1,950.00 F
3	1		*FRT BUMPER (WCP)	Distorted	450.00 F	*450.00 F
4	1		*FRT BUMPER RETAINER LH (WCP)	Cracked	25.00 F	*25.00 F
5	10		*FRT BUMPER CLIP (WCP)	Necessary	35.00 F	*35.00 F
6	1		*FRT BUMPER LOWER SPOILER (WCP)	Not Necessary	395.00 F	*- F
7	1		*FRT BUMPER FOG LAMP GARNISH LH (WCP)	Twisted	95.00 F	*95.00 F
8	1		*FRT BUMPER INNER SPONGE (WCP)	Torn	145.00 F	*145.00 F
9	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	395.00 F	*395.00 F
10	1		*HEADLAMP SUPPORT PANEL (WCP)	Repair	430.00 F	*- F
11	1		*FRT LH FENDER (WCP)	Bent	420.00 F	*420.00 F
12	1		*FRT LH FENDER INNER COWLING (WCP)	Torn	110.00 F	*110.00 F
13	10		*INNER COWLING CLIP (WCP)	Necessary	30.00 F	*30.00 F
14	1		*FRT LH FENDER PROTECTOR (WCP)	Distorted	230.00 F	*230.00 F
15	1		*FRT BUMPER FOG LAMP LH (WCP)	Cracked	230.00 F	*230.00 F
16	1		*FRT BUMPER PARKING SENSOR LH (WCP)	Shorted	230.00 F	*265.00 F
17	1		*FRT BUMPER TOW COVER (WCP)	Not Necessary	30.00 F	*- F
<u>Supplementary #1</u>						
18	1		*LH RELAY BOX LOWER (WCP)	Cracked	50.00 F	*50.00 F

F=Franchise part.

Sub Total (\$\$)	5,970.00	4,430.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	597.00	443.00
Total Parts (\$\$)	6,567.00	4,873.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	WHEEL ALIGNMENT	New	80.00	0.00
3	LABOUR CHARGE	New	600.00	500.00
4	SPRAY PAINTING	New	850.00	700.00
Supplementary #1				
Labour Items				
5	REPLACE RELAY BOX	New	50.00	50.00
Gross Labour Cost (\$)			1,610.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >