

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22003135/ENY3E2

**Date:** 10/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SNA00011082102

**Claimant Vehicle  
No :** SMY9414U

**Insured Vehicle  
No :** PC2274H

Date of Loss: 01/04/2022

Nature of Claim: TP

Claim  
No: SNM22D202313/C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY9414U**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 2NR5505498

Reg. Date: 31/03/2021 (Man. Year: 2021)

Chassis No: MR2B23F3601222289

Colour: Red

Odometer: 11871 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,398.40	2,119.50	278.90	11.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,310.00	5,705.00	1,605.00	21.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,708.40</b>	<b>7,824.50</b>	<b>1,883.90</b>	<b>19.40</b>
<b>+ GST 7.00/7.00% (S\$)</b>	679.59	547.72	131.87	19.40
<b>Nett Amount (S\$)</b>	<b>10,387.99</b>	<b>8,372.22</b>	<b>2,015.77</b>	<b>19.40</b>

### INSPECTION

Date of Assignment: 05/04/2022

Date Inspected: 04/05/2022 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462

Estimated Period of Repair: 8.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
<b>Parts:</b> 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMY9414U)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
3	1		*COVER, RR BUMPER L/C	Crushed	557.70 FS	*557.70 FS
4	2		*TAPE, MOULDING, NO.1	Not Necessary	94.60 FS	*- FS
5	1		*RETAINER, RR BUMPER	Not Necessary	164.30 FS	*- FS
6	1		*PANEL SUB-ASSY, QUAR	Dented	963.70 FS	*963.70 FS
7	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	216.00 FS	*216.00 FS
8	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS
9	1		*DAM, BACK WINDOW GLA	Necessary	34.90 FS	*34.90 FS
10	1		*DAM, BACK WINDOW GLA	Necessary	17.20 FS	*17.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **2,398.40** **2,119.50**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHK WIRING SYSTEM AND CONDUCT WATER TEST	New	180.00	180.00
2	RESET AND REPROGRAMME ECU	New	180.00	180.00
3	DRILL HOLE TO INSTALL REVERSE SENSOR	New	180.00	180.00
4	REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR	New	360.00	360.00
5	REMOVE AND REINSTALL REAR W/SCREEN GLASS TO ASSIST REPAIR	New	450.00	450.00
6	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, R/R FENDER AND AFFECTED PORTION OF CAR	New	3,600.00	2,880.00
7	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,360.00	1,475.00
			<b>Gross Labour Cost (\$\$)</b>	<b>7,310.00</b>
				<b>5,705.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >