

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003137/AVY3M4**Date:** 21/07/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00241252100
Claimant Vehicle No :	SGN9999C	Insured Vehicle No :	SMU6434C
Date of Loss:	02/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202289/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN9999C	Engine No:	1ZRY243870
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104543680
Reg. Date:	19/08/2016 (Man. Year: 2015)	Odometer:	108376 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,971.92	12,410.10	12,561.82	50.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,370.00	3,350.00	5,020.00	59.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,341.92	15,760.10	17,581.82	52.73
Approved Total (Overridden) (S\$)		12,600.00		
Nett Amount (S\$)	33,341.92	12,600.00	20,741.92	62.21

INSPECTION

Date of Assignment:	05/04/2022	
Date Inspected:	06/04/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Jul 2022)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SGN9999C)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	515.10 FL	*515.10 FL
2	2		*FRONT BUMPER FOG LAMP	Not Necessary	595.60 FL	*- FL
3	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	273.20 FL	*- FL
4	1		*FRONT BUMPER LOGO	Necessary	74.20 FL	*74.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Deformed	210.70 FL	*210.70 FL
6	1		*FRONT GRILLE TOP RUBBER	Not Necessary	79.40 FL	*- FL
7	1		*FRONT BUMPER BOTTOM COVER	Not Necessary	217.30 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	118.80 FL	*118.80 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	397.30 FL	*397.30 FL
10	1		*FRONT RADIATOR GRILLE C/W CHROME	Cracked	676.10 FL	*466.00 FL
11	2		*FRONT FENDER	Repair	1,300.00 FL	*- FL
12	2		*FRONT FENDER INNER COWLING	Not Necessary	368.40 FL	*- FL
13	1		*BONNET	Buckled	1,040.40 FL	*1,040.40 FL
14	2		*BONNET STOPPER	Not Necessary	38.40 FL	*- FL
15	1		*BONNET LOCK	Not Necessary	145.10 FL	*- FL
16	1		*BONNET LOCK BRACE PANEL	Bent	160.70 FL	*160.70 FL
17	2		*HORN	Not Necessary	216.80 FL	*- FL
18	2		*HEADLAMP	Cracked	5,699.60 FL	*5,699.60 FL
19	4		*HEAD LAMP LOWER BRACKET	Not Necessary	313.60 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Buckled	997.20 FL	*997.20 FL
21	1		*AIR CONDENSOR	Dented	1,495.60 FL	*1,121.00 FL
22	1		*RADIATOR	Not Necessary	1,780.40 FL	*- FL
23	2		*RADIATOR TOP BRACKET	Not Necessary	120.40 FL	*- FL
24	4		*RADIATOR MOUNTING	Not Necessary	260.40 FL	*- FL
25	1		*RADIATOR TOP GARNISH	Not Necessary	227.90 FL	*- FL
26	1		*TEMPERATURE SENSOR	Not Necessary	198.40 FL	*- FL
27	1		*REAR BUMPER	Deformed	535.90 FL	*535.90 FL
28	2		*REAR BUMPER REFLECTOR	Cracked	150.20 FL	*150.20 FL
29	2		*REAR BUMPER SIDE RETAINER	Not Necessary	210.20 FL	*- FL
30	1		*REAR BUMPER REINFORCEMENT	Dented	395.10 FL	*395.10 FL
31	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	180.20 FL	*- FL
32	2		*REVERSE SENSOR	Damaged	622.20 FL	*450.00 FL
33	2		*REVERSE SENSOR HOLDER	Necessary	138.60 FL	*50.00 FL
34	1		*REVERSE SENSOR WIREHARNES	Not Necessary	437.50 FL	*- FL
35	1		*BOOTLID	Buckled	756.10 FL	*756.10 FL
36	1		*BOOTLID DETECTOR	Cracked	385.00 FL	*195.00 FL
37	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
38	1		*BOOTLID EMBLEM COROLLA	Necessary	70.00 FL	*70.00 FL
39	1		*BOOTLID EMBLEM ALTIS	Necessary	70.00 FL	*70.00 FL
40	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
41	1		*BOOTLID TOP LOCK	Damaged	318.10 FL	*318.10 FL
42	1		*BOOTLID LOWER LOCK	Not Necessary	20.00 FL	*- FL
43	1		*BOOTLID WEATHERSTRIP	Cut	195.00 FL	*195.00 FL
44	2		*TAILLAMP	Cracked	930.00 FL	*930.00 FL
45	2		*TAILLAMP PANEL	Not Necessary	396.00 FL	*- FL
46	2		*TAILLAMP LOWER BARCKET	Not Necessary	230.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*REAR FENDER INNER COWLING	Not Necessary	700.40 FL	*- FL
48	2		*REAR FENDER INNER TRIM	Not Necessary	1,540.20 FL	*- FL
49	1		*REAR END PANEL	Dented	695.30 FL	*695.30 FL
50	1		*REAR END PANEL TOP GARNISH	Deformed	250.10 FL	*250.10 FL
51	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	271.10 FL	*- FL
52	1		*REAR FLOOR PANEL	Not Necessary	940.20 FL	*- FL
53	1		*REAR FLOOR SIDE PANEL RH	Not Necessary	294.60 FL	*- FL
54	1		*REAR EXHAUST PIPE	Not Necessary	930.20 FL	*- FL
55	1		*REAR EXHAUST INSULATOR	Not Necessary	147.10 FL	*- FL
56	1		*REAR EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
57	4		*REAR EXHAUST MOUNTING	Not Necessary	220.40 FL	*- FL
58	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*50.00 FS
59	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
60	1		*SET FRONT RADIATOR GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
61	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
62	1		*BONNET LOCK BRACE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*SET BONNET INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
64	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
65	1		*SET RADIATOR TOP COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
66	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
67	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
68	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
69	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
70	1		*SET TAILLAMP CLIPS	Not Necessary	60.00 FS	*- FS
71	1		*TAILLAMP PANEL SEALANT RH	Not Necessary	60.00 FS	*- FS
72	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
73	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
74	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
75	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
76	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
77	1		*BREAKDOWN TRIANGLE SIGN	Not Necessary	180.00 FS	*- FS
78	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
79	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,435.90	16,396.80
- List Item Discount on L Items 25.00/25.00% (\$)	7,463.98	3,986.70
Total Parts (\$)	24,971.92	12,410.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS (FRONT)	New	1,200.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,200.00	600.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS (FRONT)	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	30.00
6	PANEL BEATING, REMOVAL AND REPLACING PARTS (REAR)	New	2,000.00	850.00
7	TO SPRAY PAINT AFFECTED AREA (REAR)	New	1,800.00	800.00
8	TUFF COAT (REAR)	New	250.00	60.00
9	WIRING CHECK (REAR)	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR (REAR)	New	350.00	60.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)	New	80.00	50.00
13	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
14	TRANSFER BOOTLID MECHANISM (REAR)	New	80.00	0.00
15	CONDUCT WATER LEAKAGE TEST (REAR)	New	100.00	0.00
16	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT (REAR)	New	80.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE (REAR)	New	180.00	0.00
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC (REAR)	New	280.00	0.00
			Gross Labour Cost (\$\$)	8,370.00
				3,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >