

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 7680D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	1,128.00	481.25
2	REAR BUMPER BRACKET @ \$49.80	NOT NECESSARY	99.60	-
2	REAR BUMPER REFLECTOR @ \$118.60	NOT DAMAGED	237.20	-
1	REAR BUMPER REINFORCEMENT	BENT	531.50	337.00
1	REAR BUMPER INNER SPONGE	NO SUCH PARTS	240.00	-
1	REAR END PANEL	NOT DAMAGED	923.60	-
1	REAR END PANEL TOP GARNISH	NOT DAMAGED	357.40	-
	LESS 25% DISCOUNT		-879.32	-204.56
			2,637.98	613.69
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE RETAINER @ \$185.00 (SN)	NECESSARY	370.00	171.20
2	REAR BUMPER REVERSE SENSOR @ \$250.00 (SN)	SHORT CIRCUIT	500.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	UPHOLSTERY (SN)	NOT NECESSARY	300.00	-
			1,450.00	401.20
	<u>LABOUR</u>			
	R&R REAR BUMPER REVERSE SENSORS.		100.00	60.00
	CHECK WIRING.	NOT NECESSARY	100.00	-
	PANEL BEATING.		1,200.00	400.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,200.00	200.00
			2,800.00	660.00
	GRAND TOTAL		6,887.98	1,674.89

Report Ref No. CS/FCI22003141/Bvy3s2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,350.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI22003141/Bvy3s2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser