7/19/22, 12:21 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22003142/UEA3Q2

19/07/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0000491

Claimant Vehicle YN8329E Insured Vehicle No: SJR2516C No:

Date of Loss: 01/04/2022 Nature of Claim: TP Claim No: MFL2022D0001826

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN8329E

Make & Model: ISUZU NHR85AUE4A, 3.0 D (M) Engine No: 4JJ11Y7693

Reg. Date: 06/08/2015 (Man. Year: 2015) Chassis No: JAANHR85EF7100196

Colour: White Odometer: 312500 km

Engine Capacity: 2999 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R14 (D) Windforce 6 mm Front Left Side: Rear Left Side: Windforce 6/6 mm Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,525.00	590.00	1,935.00	76.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,315.00	1,000.00	315.00	23.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,840.00	1,590.00	2,250.00	58.59
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	3,840.00	1,250.00	2,590.00	67.45
+ GST 7.00/7.00% (S\$)	268.80	87.50	181.30	67.45
Nett Amount (S\$)	4,108.80	1,337.50	2,771.30	67.45
+ Loss of Use (5.0 x S\$	120.00/day) (S\$)	600.00		
N	ett Liability (S\$)	1,937.50		

INSPECTION

Date of Assignment: 05/04/2022

Jin Auto Services Pte Ltd (Defu) Date Inspected: 05/04/2022 Inspected At: Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Jun 2022)

Parts: N/A ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN8329E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,150.00 F	*- FL
2	1		*TAILGATE LOWER MEMBER	Repair	550.00 F	*- FL
3	1		*REAR BUMPER	Bent	580.00 FS	*580.00 FS
4	1		*COMPANY ADVERTISEMENT (KIV)	Necessary	200.00 FS	*- FS
5	1		*SET 60KM/HR	Necessary	15.00 FS	*10.00 FS
6	1		*SET NUMBER PLATE	Serviceable	30.00 F	*- FL
F=Fra	anchise	part. S=SpcNe	tt. L=ListItemDisc.	_		
				Sub Total (S\$)	2,525.00	590.00
			- List Item Discount or	L Items 0.00/5.00% (S\$)	0.00	0.00
				Total Parts (S\$)	2,525.00	590.00
			Report was unsubmitted du		2,525.00	
			Report was unsubmitted du	iring iriis print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO SPRAY PAINTING	New	600.00	480.00
2	CHECK HARNESS	New	35.00	20.00
3	LABOUR CHARGES TO REMOVE AND RENEW PART	New	680.00	500.00
		Gross Labour Cost (S\$)	1,315.00	1,000.00
	Report was unsubm	nitted during this print-out.		

< END OF ESTIMATES >