5/26/22, 3:28 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22003143/REA3Q2

CYV643110

Date: 26/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_01

Claimant Vehicle SLG6292E Insured Vehicle No: SNC2852M

Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: MFL2022D0001858

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG6292E

Make & Model: VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI DSG Engine No:

(A)

Reg. Date: 23/01/2020 (Man. Year: 2019) Chassis No: WVWZZZ16ZKM509501

Colour: Red Odometer: 22694 km

Engine Capacity: 1197 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

Global Sum Settlement (S\$)

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,918.82	7,523.59	395.23	4.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,710.00	4,500.00	4,210.00	48.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,628.82	12,023.59	4,605.23	27.69
+ GST 7.00/7.00% (S\$)	1,164.02	841.65	322.37	27.69
Nett Amount (S\$)	17,792.84	12,865.24	4,927.60	27.69
				<u>'</u>

INSPECTION

Date of Assignment: 05/04/2022

Volkswagen Group Singapore Pte Ltd (tuas) (HQ)

Date Inspected: 06/04/2022 Inspected At: 17 Tuas Ave 9

Singapore 639197

0.00

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 May 2022)

Parts: N/A VOLKSWAGEN BEETLE CABRIOLET 1.2 TSI DSG (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SLG6292E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Part

	Qty	No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Scratched	1,513.82 FS	*1,513.82 FS
2	1		*GUIDE PIECE FRT LHS BUMPER BRACKET	*Check	41.09 FS	*-FS
3	1		*GUIDE PIECE FRT RHS BUMPER BRACKET	Not Necessary	41.09 FS	*-FS
4	1		*HOLDER FOR COVER BUMPER FRT LHS BUMPER INNER BRACKET	*Check	52.29 FS	*-FS
5	1		*HOLDER FOR COVER BUMPER FRT RHS BUMPER INNER BRACKET	Not Necessary	52.29 FS	*-FS
6	1		*GRILLE BLACK /SATIN BLACK /FRT LHS FOG LIGHT GRILLE	Not Necessary	208.47 FS	*-FS
7	1		*GAS DISCHARGE HEADLIGHT W FRT LHS HEADLIGHT	Cracked	3,333.67 FS	*3,333.67 FS
8	1		*FENDER FRT LHS FENDER	Buckled	654.51 FS	*654.51 FS
9	1		*CROSS SUPPORT FRT LHS FENDER BRACKET	Necessary	78.11 FS	*78.11 FS
10	1		*WHEELHOUSE LINER FRT LHS WHEEL LINING	Deformed	199.58 FS	*199.58 FS
11	1		*ALLOY WHEEL BLACK -GLOSSY RIM	Scratched	1,743.90 FS	*1,743.90 FS
F=Fra	anchise	part. S=S	SpcNett.			
				Total Parts (S\$)	7,918.82	7,523.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	B&P WHEEL ALIGNMENT	New	360.00	360.00
2	R&R TYRE	New	50.00	0.00
3	ALIGN AND HEADLIGHT	New	100.00	100.00
4	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
5	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
6	TYRES/235/45R18	New	880.00	0.00
7	LABOURS	New	3,360.00	1,680.00
8	SPRAY PAINTING	New	3,200.00	1,600.00
		Gross Labour Cost (S\$)	8,710.00	4,500.00
	Report was unsub	omitted during this print-out.		

< END OF ESTIMATES >