

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3008X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER PAD REAR LH A (SN)	NOT NECESSARY	844.00	-
1	BUMPER PAD REAR RH A (SN)	NOT NECESSARY	844.00	-
1	BUMPER COVER REAR XC (SN)	CUT	1,865.70	1,679.13
1	V031449334/PROTECTIN (SN)	CUT	780.10	702.09
1	TOW COVER REAR XC40 (SN)	CUT	89.80	80.82
1	BUMPER REFLECTOR LH (SN)	BROKEN	170.50	153.45
10	EXPANDING NUT XC40 1 (SN)	NOT NECESSARY	67.00	-
1	V032291556/BUMPER RA (SN)	NOT NECESSARY	1,621.60	-
4	PARK SENSOR FRT/REAR (SN)	NOT NECESSARY	452.80	-
1	CABLE HARNESS BUMPER (SN)	NOT NECESSARY	205.50	-
1	BUMPER INSTALLING MT (SN)	NECESSARY	101.40	91.26
10	BUMPER CLIP 8X8,5 (SN)	NECESSARY	82.00	73.80
10	WIPER GRILLE CLIP XC (SN)	NECESSARY	88.00	79.20
10	BLIND RIVET 4.0*21 P (SN)	NECESSARY	50.00	45.00
1	HEAT SHIELD REAR XC4 (SN)	NOT NECESSARY	257.70	-
1	ROOF SPOILER XC40 (SN)	BROKEN	1,216.70	1,216.70
1	DRIVE UNIT TAILGATE (SN)	BROKEN	1,016.20	914.58
1	DRIVE UNIT TAILGATE (SN)	NOT NECESSARY	1,016.20	-
1	EMBLEM "VOLVO" REAR (ADDITIONAL)(SN)	NECESSARY	109.62	109.62
1	EMBLEM "XC40" 18 (ADDITIONAL)(SN)	NECESSARY	124.56	124.56
1	EMBLEM "T5" XC60 S80 (ADDITIONAL)(SN)	NECESSARY	105.30	105.30
1	EMBLEM "AWD" XC90 16 (ADDITIONAL)(SN)	NECESSARY	101.07	101.07
			11,209.75	5,476.58
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER,REAR LOWER SPOILER,REAR SKID PLATE,ETC.		2,550.00	1,700.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC.		2,250.00	1,500.00
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-

Report Ref No. CS/SMR22003144/Evy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		555.00	555.00
			5,415.00	3,755.00
	GRAND TOTAL		16,624.75	9,231.58
	RECOMMENDED COST OF REPAIRS			9 231 58

Report Ref No. CS/SMR22003144/Evy3n2



Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator