

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG22003145/KPA3Q2  
**Date:** 28/10/2022

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000036  
**Claimant Vehicle No :** GBE2260C **Insured Vehicle No :** GBG1527E  
Date of Loss: 01/04/2022 Nature of Claim: TP Claim No: 7148944025SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBE2260C**  
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2557144  
Reg. Date: 02/10/2015 (Man. Year: 2015) Chassis No: JTFAT35YX0K205056  
Colour: Silver Odometer: 355444 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)  
Front Left Side: Yokohama 9 mm Rear Left Side: POWERTRAIN 3/3 mm  
Front Right Side: Yokohama 9 mm Rear Right Side: POWERTRAIN 3/3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,952.10	3,732.10	220.00	5.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	2,050.00	500.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,502.10</b>	<b>5,782.10</b>	<b>720.00</b>	<b>11.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>(S\$)</b>	6,502.10	4,600.00	1,902.10	29.25
<b>+ GST 7.00/7.00% (S\$)</b>	455.15	322.00	133.15	29.25
<b>Nett Amount (S\$)</b>	<b>6,957.25</b>	<b>4,922.00</b>	<b>2,035.25</b>	<b>29.25</b>
<b>+ Loss of Use (7.0 x S\$70.00/day) (S\$)</b>		490.00		
<b>Nett Liability (S\$)</b>		<b>5,412.00</b>		

**INSPECTION**

Date of Assignment: 20/05/2022  
Date Inspected: 20/05/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,185.00 FL	*1,185.00 FL
2	1		*REAR TAILGATE LOCK RH	Bent	100.30 FL	*100.30 FL
3	1		*REAR TAILGATE LOCK HANDLE RH	Distorted	66.70 FL	*66.70 FL
4	1		*TAILLAMP RH	Cracked	221.90 FL	*221.90 FL
5	1		*TAILLAMP PANEL RH	Bent	64.70 FL	*64.70 FL
6	1		*RH SIDE GATE	Bent	1,492.20 FL	*1,492.20 FL
7	1		*STICKER -13 PAX	Necessary	12.00 FS	*12.00 FS
8	1		*STICKER -70KM/H	Necessary	12.00 FS	*12.00 FS
9	1		*TAILGATE INNER PROTECTOR	Necessary	280.00 FS	*280.00 FS
10	18		*TAILGATE INNER PROTECTOR RIVET	Necessary	54.00 FS	*54.00 FS
11	1		*REVERSE CAMERA	Serviceable	200.00 FS	*- FS
12	1		*REAR NUMBER PLATE	Serviceable	20.00 FS	*- FS
13	1		*REAR CORNAL STOPPER RH	Missing	22.00 FS	*22.00 FS
14	1		*REAR RH SIDE GATE INNER PROTECTOR	Necessary	350.00 FS	*350.00 FS
15	18		*REAR RH SIDE GATE INNER PROTECTOR RIVET	Necessary	54.00 FS	*54.00 FS
16	1		*REAR FLOOR BOARD PROTECTOR	Bent	600.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,734.80</b>	<b>4,514.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	782.70	782.70
<b>Total Parts (\$)</b>	<b>3,952.10</b>	<b>3,732.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIX REAR FULL CANOPY ,FLOOR BOARD PROTECTOR ,RR TRUCK ASSY ,TO CUT ,WELD KNOCK & REPAIR RR END MEMBER ,TAILGATE LOWER PANEL ,RHSIDE PANEL CABIN RR RH PILLAR AND RE-ALIGN TO SAME	New	1,000.00	850.00
2	TO PUTTY AND RESPRAY ON TAILGATE RH SIDE GATE ,LOWER MEMBER ,RR FLOOR BOARD PANEL CABIN RR PANEL ,RH PILLAR AND ALL AFFECTED AREAS	New	1,000.00	800.00
3	TO REWRITE ADVERTISEMENT	New	350.00	220.00
4	TO REPAIR ,REALIGN REAR CANOPY	New	200.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,550.00</b>	<b>2,050.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**