

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22002032/TTY3E2-1

Date: 26/04/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0000974
Claimant Vehicle No : SLG7183E Insured Vehicle No : SLL8980M
Date of Loss: 01/03/2022 Nature of Claim: TP Claim No: MFL2022D0001212

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG7183E**
Make & Model: HONDA GRACE, 1.5 HYBRID DX CVT ABS D/AIRBAG (A) Engine No: LEB5254655
Reg. Date: 11/10/2016 (Man. Year: 2016) Chassis No: GM41104643
Colour: White Odometer: 165821 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,432.16	832.08	1,600.08	65.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	920.00	1,590.00	63.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,942.16	1,752.08	3,190.08	64.55
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	4,942.16	1,400.00	3,542.16	71.67

INSPECTION

Date of Assignment: 05/04/2022
Date Inspected: 10/03/2022 Inspected At: Hock Motors Workshop (HQ)
NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY
@ KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2022)

Parts: 192 HONDA GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG7183E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S TAILLAMP	Damaged	488.30 FL	*381.70 FL
2	1		*REAR END PANEL	Repair	800.60 FL	*- FL
3	1		*REAR BUMPER	Damaged	845.00 FL	*463.70 FL
4	1		*REAR BUMPER N/S SIDE RETAINER	Necessary	65.80 FL	*65.80 FL
5	1		*REAR BUMPER REFLECTOR	Damaged	60.90 FL	*60.90 FL
6	1		*REAR N/S FENDER	Repair	711.60 FL	*- FL
7	1		*REAR N/S FENDER INNER AIR VENT	Damaged	68.00 FL	*68.00 FL

F=Franchise part. L=ListItemDisc.

	Sub Total (S\$)	3,040.20	1,040.10
	- List Item Discount on L Items 20.00/20.00% (S\$)	608.04	208.02
	Total Parts (S\$)	2,432.16	832.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	30.00
4	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	80.00	0.00
5	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,080.00	400.00
6	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
			Gross Labour Cost (\$\$)	2,510.00
				920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >