

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003148/AVY3N2**Date:** 30/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00061342102
<b>Claimant Vehicle No :</b>	GBG5440U	<b>Insured Vehicle No :</b>	GBJ6133J
Date of Loss:	31/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202257/C02/CHEESC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBG5440U</b>	Engine No:	1KD2745102
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Chassis No:	JTFHT02P000231881
Reg. Date:	30/08/2017 (Man. Year: 2017)	Odometer:	201132 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,442.20	4,285.92	9,156.28	68.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	1,860.00	2,240.00	54.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,542.20</b>	<b>6,145.92</b>	<b>11,396.28</b>	<b>64.96</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,900.00</b>		
<b>Nett Amount (\$\$)</b>	<b>17,542.20</b>	<b>4,900.00</b>	<b>12,642.20</b>	<b>72.07</b>

**INSPECTION**

Date of Assignment:	05/04/2022	
Date Inspected:	06/04/2022 Inspected At:	KS AUTOMOBILE (HQ) 60 JALAN LAM HUAT, CARROS CENTRE, #05-68 Singapore 737869
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5440U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,754.00 FL	*1,754.00 FL
2	1		*TAILGATE OUTER HANDLE	Not Necessary	194.20 FL	*- FL
3	1		*TAILGATE OUTER MOULDING	Cut	312.00 FL	*312.00 FL
4	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	119.20 FL	*- FL
5	1		*TAILGATE INNER TRIM	Not Necessary	267.60 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	368.00 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP PROTECTOR	Not Necessary	99.60 FL	*- FL
8	1		*TAILGATE INNER LOCK	Jammed	257.60 FL	*257.60 FL
9	1		*TAILGATE LOWER LOCK	Not Necessary	100.20 FL	*- FL
10	1		*TAILGATE KEY LOCK	Not Necessary	241.60 FL	*- FL
11	1		*TAILGATE WINDSCREEN RUBBER	Necessary	294.00 FL	*294.00 FL
12	1		*TAILGATE LOGO	Necessary	59.00 FL	*59.00 FL
13	1		*TAILGATE INNER TOP TRIM	Not Necessary	284.00 FL	*- FL
14	1		*TAIL GATE CAMERA	Not Necessary	845.00 FL	*- FL
15	2		*TAIL LAMP	Cracked	595.20 FL	*595.20 FL
16	1		*TAIL LAMP PANEL RH	Repair	387.90 FL	*- FL
17	1		*REAR FLOOR MAT	Not Necessary	800.00 FL	*- FL
18	1		*REAR BUMPER	Distorted	598.00 FL	*598.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	134.40 FL	*134.40 FL
20	1		*REAR FENDER INNER PANEL	Repair	679.40 FL	*- FL
21	1		*REAR END PANEL (INNER)	Repair	547.10 FL	*- FL
22	1		*REAR END PANEL (OUTER)	Dented	850.20 FL	*645.00 FL
23	1		*REAR END PANEL EXTEND PANEL	O/s Dented	797.40 FL	*398.70 FL
24	1		*REAR FLOOR PANEL	Repair	2,298.00 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	898.00 FL	*- FL
26	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	56.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
28	8		*REAR BUMPER CLIP	Necessary	52.00 FS	*30.00 FS
29	1		*REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
30	8		*TAILGATE INNER BOARD CLIP	Necessary	52.00 FS	*30.00 FS
31	1		*TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE STICKER 70KM/H	Necessary	20.00 FS	*15.00 FS
33	1		*TAILGATE STICKER 8 PAX	Necessary	20.00 FS	*15.00 FS
34	1		*SET TAILGATE COMPANY STICKER	Necessary	200.00 FS	*120.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
36	1		*REAR END PANEL TOP PLATE	Not Necessary	300.00 FS	*- FS
37	1		*REAR END PANEL EXTEND PANEL SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR FLOOR PANEL TOP WOODEN (SPECIAL TYPE)	Not Necessary	600.00 FS	*- FS
39	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
41	1		*REAR FLOOR TOP BOARD	Not Necessary	800.00 FS	*- FS
42	1		*REAR FLOOR PANEL SEALANT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,901.60	5,547.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,459.40	1,261.98

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>13,442.20</b>
						<b>4,285.92</b>
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING AND REPLACE PARTS	New	1,600.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	80.00
4	WIRING,BULB CHECKING	New	80.00	0.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
6	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REAR EXHAUST	New	150.00	0.00
9	REAR CHASSIS ALIGHMENT	New	250.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,100.00</b>	<b>1,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >