



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300881

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/02/2023
Reference CC6/CTI22003149/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 5017J
Insured Veh. GBH 7109J
Claim No. SNM22D202335/C02
Policy No. DMCVSNW00026242200
Accident Date 04/04/2022
Inspection Date 05/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI22003149/Tpa3q2	
			Date: 15/02/2023	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 7109J	Veh. Inspected	SLM 5017J	
Policy No.	DMCVSNW00026242200	Coverage (\$)	0.00	
Claim No.	SNM22D202335/C02	Excess (\$)	0.00	
Assign From		Assign Date	05/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJGK85GG083544	Colour	SILVER	
Odometer	113587 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2022	Inspection Date	05/04/2022	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 5017J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	550.00	550.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER BRACKET	DISTORTED	25.00	25.00
1	REAR BUMPER RETAINER RH	DEFORMED	20.00	20.00
1	REAR BUMPER RETAINER LH	DEFORMED	20.00	20.00
1	REAR REINFORCEMENT	BENT	350.00	350.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	38.00	-
1	REAR BUMPER REFLECTOR LH	CRACKED	38.00	38.00
1	TAIL LAMP RH	NOT NECESSARY	480.00	-
1	TAIL LAMP LH	CRACKED	480.00	480.00
4	TAIL LAMP SPECIAL CLIPS @\$6.00	NECESSARY	24.00	24.00
1	TAILGATE	BENT	1,280.00	1,072.00
1	TAILGATE HINGE RH	TO REPAIR SEE LABOUR	50.00	-
1	TAILGATE HINGE LH	TO REPAIR SEE LABOUR	50.00	-
1	TAILGATE ABSORBER RH	NOT NECESSARY	195.00	-
1	TAILGATE ABSORBER LH	NOT NECESSARY	195.00	-
1	TAILGATE LOCK	JAMMED	560.00	395.00
1	TAILGATE STRIKER	NOT NECESSARY	35.00	-
1	TAILGATE SWITCH OPENER ASSY -63270SG010	CRACKED	110.00	110.00
1	TAILGATE RUBBER SEAL	NOT NECESSARY	135.00	-
1	TAILGATE UPPER TRIM GARNISH	MISSING	270.00	270.00
14	TAILGATE UPPER TRIM GARNISH SPECIAL CLIPS @ \$7.00	NECESSARY	98.00	98.00
1	TAILGATE SPOILER	NOT NECESSARY	880.00	-
1	TAILGATE LOWER INNER TRIM	DEFORMED	250.00	250.00
1	TAILGATE UPPER INNER TRIM	NOT NECESSARY	90.00	-
1	REAR SUBARU & AWD EMBLEM	NECESSARY	90.00	90.00
1	REAR FORESTER XT EMBLEM	NECESSARY	90.00	90.00
1	REAR WINDSCREEN WIPER MOTOR	BENT	290.00	290.00
1	REAR WINDSCREEN WIPER ARM	CUT	68.00	68.00

Report Ref No. CC6/CTI22003149/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEEN WIPER BLADE	CUT	45.00	45.00
1	REAR WINDSCREEEN WIPER COVER	NOT NECESSARY	15.00	-
1	REAR WINDSCREEN	CRACKED	1,450.00	1,120.80
1	REAR WINDSCREEN MOULDING ASSY	NECESSARY	70.00	70.00
1	END PANEL TOP GARNISH	DEFORMED	60.00	60.00
1	END PANEL	BENT	350.00	350.00
1	SPARE TYRE BOARD	NOT NECESSARY	280.00	-
1	REAR FLOOR PANEL	BUCKLED	450.00	450.00
1	REAR FLOOR SPONGE RH (ADDITIONAL)	CRACKED	80.00	80.00
1	REAR FLOOR SPONGE LH (ADDITIONAL)	CRACKED	80.00	80.00
1	REAR BOOT SIDE TRIM RH (ADDITIONAL)	CRACKED	350.00	350.00
1	REAR BOOT SIDE TRIM LH (ADDITIONAL)	CRACKED	350.00	350.00
1	REAR TRICK COVER (ADDITIONAL)	CRACKED	180.00	180.00
1	JACK HOLDER ASSY (ADDITIONAL)	CRACKED	160.00	160.00
1	EXHAUST MUFFLER ASSY LH (ADDITIONAL)	BENT	1,350.00	668.00
1	REAR TOW EYE COVER (ADDITIONAL)	MISSING	50.00	50.00
1	TAIL LAMP PANEL LH (ADDITIONAL)	TO REPAIR SEE LABOUR	360.00	-
1	EXHAUST MUFFLER HEAT SHIELD COVER LH (ADDITIONAL)	BENT	120.00	120.00
1	REAR TAILGATE SWITCH BRACKET GARNISH (ADDITIONAL)	CRACKED	120.00	120.00
	LESS 20% DISCOUNT		-	-1,708.76
			12,731.00	6,835.04
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENSE PLATE WITH CASING (SN)	BENT	40.00	40.00
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	REAR BLACKVUE CAMERA (SN) (ADDITIONAL)	MISSING	400.00	350.00
1	SEALANT (END PANEL ,SPARE TYRE SINK,REAR CHASSIS LH & REAR FENDER LH) (SN) (ADDITIONAL)	NECESSARY	250.00	150.00
1	BRIDGESTONE TYRE 185/65R17 90M (SN) (ADDITIONAL)	NOT NECESSARY	200.00	-
			1,090.00	740.00

Report Ref No. CC6/CTI22003149/Tpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SPRAY PAINT (WHOLE REAR ,INNER PANELS & ROOF PANEL).		1,400.00	1,300.00
	REMOVE,REFIT ,REPAIR AND REPLACE ACCIDENT AFFECTED PARTS .INCLUSIVE OF THE REPAIR OF TAILGATE HINGE RH,TAILGATE HINGE LH AND TAIL LAMP PANEL LH .		1,000.00	900.00
	TRANSFER TAILGATE FITTING & WINDOW MECHANISM TO NEW TAILGATE.		100.00	60.00
	REMOVE & REFIT UPHOLSTERY ,GARNISHES ,TRIMMING TO FACILITATE REPAIR.		250.00	60.00
	COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	40.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
	REMOVE ,REPLACE & REFIT EXHAUST MUFFLER LH . (ADDITIONAL)		150.00	80.00
	CUT ,WELD & RE-ALIGN END PANEL & SPARE TYRE SINK .(ADDITIONAL)		600.00	200.00
	REPAIR & RE-ALIGN REAR CHASSIS LH & REAR FENDER LH.(ADDITIONAL)		600.00	200.00
	REMOVE ,REPLACE & REFIT EXHAUST MUFFLER HEAT SHIELD COVER & REAR TAILGATE SWITCH BRACKET GARNISH LH .(ADDITIONAL)	NOT NECESSARY	150.00	-
	CUT,WELD & RE-ALIGN END PANEL & SPARE TYRE SINK.(ADDITIONAL)	NOT NECESSARY	250.00	-
			4,710.00	2,870.00
GRAND TOTAL			18,531.00	10,445.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,350.00

Report Ref No. CC6/CTI22003149/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5017J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5017J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5017J

RE-INSPECTION

