

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003150/BTY3N2**Date:** 29/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00015012207

**Claimant Vehicle
No :** SLS6892K**Insured Vehicle
No :** GV9904J

Date of Loss: 19/03/2022

Nature of Claim: TP

Claim
No: SNM22D201933/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLS6892K**

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB982121

Reg. Date: 29/09/2017 (Man. Year: 2017)

Chassis No: ZSU600101883

Colour: Brown

Odometer: 171304 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45R20

Rear Tyre Size: 255/45R20

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,587.00	5,406.27	8,180.73	60.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,780.00	2,120.00	54.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,487.00	7,186.27	10,300.73	58.91
Approved Total (Overridden) (\$\$)		5,750.00		
(\$\$)	17,487.00	5,750.00	11,737.00	67.12
+ GST 7.00/7.00% (\$\$)	1,224.09	402.50	821.59	67.12
Nett Amount (\$\$)	18,711.09	6,152.50	12,558.59	67.12

INSPECTION

Date of Assignment: 29/04/2022

Date Inspected: 06/04/2022 Inspected At:

 160 SIN MING DR
 #01-14 SIN MING AUTO CITY
 SINGAPORE 575722
 REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS6892K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (ORIGINAL ROJAM)	Broken	3,856.20 FL	*3,480.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	268.00 FL	*- FL
3	1		*FRONT BUMPER INNER SPONGE	Not Necessary	182.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	268.50 FL	*- FL
5	1		*FRONT BUMPER LOWER LID	Not Necessary	418.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP	Not Necessary	349.00 FL	*- FL
7	1		*FRONT BUMPER PARKING SENSOR (2 Pcs)	Short Circuit (1 Pc only)	579.20 FL	*100.00 FL
8	1		*FRONT FENDER RH	Repair	1,158.70 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Not Damaged	699.40 FL	*- FL
10	1		*FRONT SUPPORT PANEL SIDE GARNISH	Broken	327.50 FL	*286.70 FL
11	1		*HEADLAMP RH	Broken	2,651.00 FL	*2,651.00 FL
12	1		*HEADLAMP LOWER BRACKET RH	Repair	256.00 FL	*- FL
13	1		*REAR BUMPER (ORIGINAL ROJAM)	FRONT BUMPER (ORIGINAL ROJAM)	3,658.50 FL	*- FL
14	1		*REAR SPOILER (ORIGINAL ROJAM)	FRONT BUMPER (ORIGINAL ROJAM)	1,500.00 FL	*- FL
15	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
16	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	2		*FRONT BUMPER SIDE RETAINER	Necessary	268.00 FS	*268.00 FS
18	1		*FRONT BUMPER WRAP STICKER	Necessary	450.00 FS	*150.00 FS
19	1		*FRONT BUMPER LED LIGHT	Not Necessary	480.00 FS	*- FS
20	1		*FRONT SUPPORT PANEL SIDE GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,630.00 7,035.70
- List Item Discount on L Items 25.00/25.00% (\$\$) 4,043.00 1,629.43

Total Parts (\$\$) 13,587.00 5,406.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
2	FRONT BUMPER PARKING SENSOR	New	100.00	60.00
3	CHECK WIRING	New	100.00	0.00
4	UPHOLSTERY	New	200.00	0.00
5	PANEL BEATING	New	1,000.00	600.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING (SPECIAL COLOUR)	New	2,000.00	1,000.00
Gross Labour Cost (\$\$)			3,900.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >