

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22003154/DPA3Q2**Date:** 19/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : GBK9292H **Insured Vehicle No :** GBH9810D

Date of Loss: 18/03/2022 Nature of Claim: TP Claim No: MFL2022D0001640

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK9292H**

Make & Model: TOYOTA HIACE, 2.8 D DX (A)

Engine No: 1GD8409560

Reg. Date: 19/12/2019 (Man. Year: 2019)

Chassis No: GDH2011022962

Colour: White

Odometer: 55953 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,829.73	0.00	22,829.73	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,920.00	600.00	6,320.00	91.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,749.73	600.00	29,149.73	97.98
+ GST 7.00/7.00% (S\$)	2,082.48	42.00	2,040.48	97.98
Nett Amount (S\$)	31,832.21	642.00	31,190.21	97.98
+ Loss of Use (4.0 x S\$70.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		960.45		

INSPECTION

Date of Assignment: 05/04/2022

Date Inspected: 07/04/2022 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2022)
Parts:	213	TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK9292H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP RH	Not Necessary	1,689.10 FL	*- FL
2	1		*HEAD LAMP WIREHARNES COMPLETE RH	Not Necessary	1,891.29 FL	*- FL
3	1		*BONNET	Not Necessary	1,180.51 FL	*- FL
4	1		*BONNET TOYOTA LOGO	Not Necessary	79.10 FL	*- FL
5	1		*BONNET SEAL	Not Necessary	81.92 FL	*- FL
6	1		*FRONT CORNER PANEL RH	Not Necessary	425.29 FL	*- FL
7	1		*FRONT SIDE PILLAR RH	Not Necessary	1,349.20 FL	*- FL
8	1		*FRONT GRILLE ASSY	Not Necessary	982.60 FL	*- FL
9	1		*FRONT LOWER GRILLE	Not Necessary	389.51 FL	*- FL
10	1		*FRONT BUMPER	Repair	749.80 FL	*- FL
11	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	206.80 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	249.80 FL	*- FL
13	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	69.80 FL	*- FL
14	1		*WIREHARNES HOUSING ASSY RH	Not Necessary	1,715.24 FL	*- FL
15	1		*FRONT DOOR RH	Not Necessary	1,951.10 FL	*- FL
16	2		*FRONT DOOR HINGE RH	Not Necessary	196.20 FL	*- FL
17	1		*FRONT BUMPER WINDOW MOULDING RH	Not Necessary	198.10 FL	*- FL
18	1		*FRONT BUMPER WEATHERSTRIP INNER RH	Not Necessary	302.10 FL	*- FL
19	1		*FRONT BUMPER WEATHERSTRIP OUTER RH	Not Necessary	298.90 FL	*- FL
20	1		*FRONT BUMPER WIREHARNES COMPLETE RH	Not Necessary	2,451.25 FL	*- FL
21	1		*FRONT DOOR STEP GARNISH	Not Necessary	342.00 FL	*- FL
22	1		*FRONT WHEEL HOUSING TOP GARNISH RH	Not Necessary	398.10 FL	*- FL
23	1		*FRONT STEP PANEL UPPER RH	Not Necessary	259.10 FL	*- FL
24	1		*FRONT STEP PANEL LOWER RH	Not Necessary	298.70 FL	*- FL
25	1		*FRONT STEP PANEL GARNISH RH	Not Necessary	198.85 FL	*- FL
26	1		*FRONT RIM RH	Not Necessary	898.00 FL	*- FL
27	1		*FRONT WHEEL BEARING RH	Not Necessary	239.80 FL	*- FL
28	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	341.20 FL	*- FL
29	1		*FRONT ABSORBER RH	Not Necessary	791.80 FL	*- FL
30	1		*FRONT LOWER ARM RH	Not Necessary	749.80 FL	*- FL
31	1		*STABILIZER LINK RH	Not Necessary	245.10 FL	*- FL
32	1		*STABILIZER BAR	Not Necessary	452.90 FL	*- FL
33	1		*STEERING RACK & PINION ASSY	Not Necessary	2,943.10 FL	*- FL
34	1		*FRONT KNUCKLE ARM RH	Not Necessary	984.50 FL	*- FL
35	1		*CENTER PILLAR RH	Not Necessary	1,892.41 FL	*- FL
36	1		*FRONT NUMBER PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
37	1		*FRONT BUMPER BODY KIT	Not Necessary	1,500.00 FS	*- FS
38	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*FRONT FRONT BUMPER LED LAMP	Not Necessary	180.00 FS	*- FS
42	1		*CENTER PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*FRONT DOOR COMPANY STICKER	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)29,702.970.00

- List Item Discount on L Items 25.00/25.00% (\$\$)6,873.240.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (\$\$)	22,829.73
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	0.00
5	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	New	400.00	0.00
6	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	400.00	0.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	400.00	0.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,920.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >