

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122003156/UQY3N2**Date:** 26/04/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SNC8575Z**Insured Vehicle No :** YN3020C

Date of Loss: 01/04/2022

Nature of Claim:

TP

Claim No: CDMCG22000616

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC8575Z**

Make &amp; Model: PORSCHE PANAMERA, 3.6 PDK (A)

Engine No: C03569

Reg. Date: 20/01/2012 (Man. Year: 2011)

Chassis No: WP0ZZZ97ZCL001590

Colour: Green

Odometer: 149017 km

Engine Capacity: 3605 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40ZR20

Rear Tyre Size: 295/35ZR20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,820.00	11,981.84	12,838.16	51.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,310.00	1,920.00	59.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,050.00</b>	<b>13,291.84</b>	<b>14,758.16</b>	<b>52.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,600.00</b>		
<b>(S\$)</b>	28,050.00	10,600.00	17,450.00	62.21
<b>+ GST 7.00/7.00% (S\$)</b>	1,963.50	742.00	1,221.50	62.21
<b>Nett Amount (S\$)</b>	<b>30,013.50</b>	<b>11,342.00</b>	<b>18,671.50</b>	<b>62.21</b>

INSPECTION

Date of Assignment: 05/04/2022

Date Inspected: 05/04/2022 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 Apr 2022)

**Parts:** 144      PORSCHE PANAMERA 3.6 PDK (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNC8575Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented/Bent	6,500.00 F	*3,966.00 FN
2	1		*BONNET LOGO	Necessary	195.00 F	*195.00 FN
3	1		*BONNET INNER RUBBER	Not Necessary	128.00 F	*- FN
4	1		*FRONT BUMPER	Distorted	4,950.00 F	*2,645.11 FN
5	1		*FRONT BUMPER FOG LAMP N/S	Cracked	850.00 F	*650.00 FN
6	1		*FRONT BUMPER INNER GARNISH N/S	Distorted	485.00 F	*392.00 FN
7	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	502.00 F	*- FN
8	1		*FRONT BUMPER SPONGE	Torn	290.00 F	*289.00 FN
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,560.00 F	*- FN
10	1		*FRONT BUMPER INNER WASHER NOZZLE N/S	Cracked	650.00 F	*490.00 FN
11	1		*FRONT BUMPER PDC SENSORS (2 Pcs)	Shorted (1 Pc only)	500.00 F	*242.00 FN
12	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*60.00 FN
13	1		*AIR CLEANER BOX ASSY	Broken	1,280.00 F	*980.00 FN
14	1		*FRONT SUPPORT PANEL	Repair	1,420.00 F	*- FN
15	1		*FRONT LICENCE PLATE	Damaged	50.00 FS	*40.00 FS
16	1		*HEADLAMP N/S	Cracked	5,400.00 F	*3,359.60 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>24,820.00</b>	<b>13,308.71</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>1,326.87</b>
<b>Total Parts (\$\$)</b>	<b>24,820.00</b>	<b>11,981.84</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRT PDC SENSOR	New	100.00	50.00
3	TO RESET & DIAGNOSTIC SYSTEM	New	180.00	100.00
4	TO SPRAY RUST PROOFING	New	80.00	40.00
5	TO REFILL AIR CON GAS	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	500.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,230.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >