

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

To: Allianz Global Corporate & Specialty SE, Singapore Branch

SPMF1000000449

Policy No: _____

04.04.2022

Date: _____

Accident Date : 29.03.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Shuttle Hybrid" Reg. No SLZ4320X			
1pc	Bonnet ✓ BUC		480.00
2pcs	Bonnet Hinges ✓ BT	22.00	44.00
1pc	Bonnet Lock ✓ BT		85.00
1pc	Bonnet Rubber Seal ✓ TN		20.00
1pc	Bonnet Insulator ✓ DE		80.00
5pcs	Bonnet Insulator Clips ✓ NEC	3.50	17.50
1pc	Grille ✓ CRA		160.00
1pc	Grille Emblem ✓ MIS		16.00
1pc	Grille Emblem Brace Bracket ?		35.00
1pc	Grille Outer Chrome Cover ✓ CUT		160.00
1pc	Grille Lower Chrome Moulding ✓ CUT		100.00
1pc	Grille Top Brace Bracket ?		75.00
2pcs	Grille Side Brackets ?	35.00	70.00
2pcs	Headlamps (LED) RH ✓ CRA / LH ?	1,300.00	2,600.00
1pc	Front Bumper ✓ CRA		480.00
10pcs	Front Bumper Clips ✓ NEC	3.50	35.00
1pc	Front Bumper Reinforcement ✓ BT		210.00
1pc	Front Bumper Center Air Grille ?		65.00
2pcs	Front Bumper Corner Retainers RH ✓ DE / LH X NN	6.00	12.00
1pc	Front Bumper Tow Point Cover ✓ MIS		12.00
2pcs	Front Bumper Fog Lamps RH ✓ MIS / LH ?	160.00	320.00
1pc	Front Bumper Fog Lamp Wiring Harness ?		462.00
1pc	Front Bumper Fog Lamp Cover ?		55.00
2pcs	Front Bumper Fog Lamp Cover Chrome Mouldings RH ✓ SCR LH ?	65.00	130.00
1pc	Front Bumper Fog Lamp Top Garnish RH ?		65.00
1pc	Front Fender RH ✓ BUC		140.00
1pc	Front Fender Shield ?		80.00
1pc	Front Fender Badge Hybrid ✓ NEC		95.00
1pc	Support Panel ?		370.00
1pc	Support Panel Top Garnish ✓ DE		35.00
1pc	Air Con Condenser ✓ BT		650.00
1pc	Air Con Condenser Side Air Guide ?		25.00
1pc	Radiator ?		750.00
1pc	Front Exterior Ambience Sensor ?		35.00
1pc	Air Cleaner Cold Intake Air Duct ✓ DE		75.00
	Cost Plus 10%		8,043.50
			804.35
			8,847.85
		C/F	8,847.85

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Accident Date : 29.03.2022

Date: 04.04.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Shuttle Hybrid" Reg. No SLZ4320X		
		B/F	8,847.85
	To Conduct Electrical Check, Focus Headlamp		30.00 ✓
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 80
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 40
	To Provide Transportation (Towing)		120.00 ?
	Labour Charge - Panel Beating, Repairing Front Chassis, Front LH Fender, Windscreen Pillar.Cnt, Weld Support & Part Replacement		800.00 600
	To Respray Affected Areas		950.00 800
		Total :	10,927.85
	5 Days		
	Lumpsum repair		
	Excess: TBA		
	Not Authorised		
	After repair photos		
	Guo Qiang - LKK		
	06/04/2022		