

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4133H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	CUT	1,409.10	1,409.10
1	FRT NUMBER PLATE GARNISH	CRACKED	188.00	188.00
1	UNIT ASSY SMART CRUISE RADAR SENSOR	TO REPAIR SEE LABOUR	2,910.90	-
1	FRT BUMPER	CUT	430.90	430.90
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	1,075.10	-
2	FRT BUMPER REINFORCEMENT ABSORBER LH RH @ \$93.25	SERVICEABLE	186.50	-
1	FRT BUMPER MOULDING CENTRE UPPER	SCRATCHED	368.50	368.50
2	FRT BUMPER BRACKET TOP LH RH @ \$35.00	NECESSARY	70.00	70.00
2	FRT BUMPER SIDE BRACKET LH RH	NECESSARY	56.00	56.00
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER CENTRE GRILLE	SCRATCHED	318.80	318.80
1	FRONT BUMPER LOWER GRILLE MOULDING	SERVICEABLE	127.60	-
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	949.30	-
1	AIRCON CONDENSER	CUT	663.60	663.60
1	AIRCON TUBE LIQUID	CUT	224.00	224.00
1	ACTIVE AIR UPPER FLAP ASSY RH	CUT	168.00	168.00
	LESS 20% DISCOUNT		-1,833.66	-783.78
			7,334.64	3,135.12
	SPECIAL NETT ITEMS			
1	FRT NUMBER PLATE WITH TRIM COVER (SN)	MISSING	55.00	55.00
			55.00	55.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF UNIT ASSY SMART CRUISE RADAR SENSOR.		1,100.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
			1,400.00	600.00
	GRAND TOTAL		8,789.64	3,790.12

Report Ref No. NS/INC22003162/Vtcs2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,050.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22003162/Vtcs2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser